



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	27/01/2026		M57 Pretoria Road - 1619
Inspection Date	27/01/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	LG99CJGP
Model	POLO VIVO 1.4 55KW TRENDLINE 5-DR [2022-2024]	Register Number	
VIN	AAVZZZ6RZPU015771	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2025
Color	GREY	Power / Displacement	
Year Model	2023	Paint Finish	TWO COAT UNI
Km Reading	120,069 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026



Damage	Repair Way
Engine Oil Sweat	Repair
Central Air Vent Damaged	Replace
Radio/CD/USB Defective	Repair
Air Conditioner Insufficient	Replace
Tail Light Left Cracked	Replace
Headlight Right Damaged	Replace
Parcel Tray Damaged	Repair
Front Bumper Residual Traces of Repair	Repair
Bonnet Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Fuel Flap Damaged	Repair
Sill Panel Left Dented	Repair
Windscreen Cracked	Replace
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	
Parking Brake Performance Left / Right Difference out of legal range	Repair
Tyre Front Left Damaged	Replace
Tyre Rear Left Damaged	Replace
Rim Front Left Scratched	Repair
Chassis Dented	Repair
Radiator Cradle Damaged	Repair
Gear Selections Malfunction	Repair
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Road test	Gearbox faulty
Body and Exterior	Front bumper stiffener damaged

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.48	3.11	-	
Rear	0.72	1.7	-	
Emergency / Parking	0.43	1.58	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60 R15	84H	Continental	Contipremuim	V	0623	4 mm
Front Right	185/60 R15	84T	Continental	Contipremuim	V	2110	1 mm
Rear Left	185/60 R15	84H	Continental	Contipremuim	V	2724	4 mm
Rear Right	185/60 R15	84H	Continental	Contipremuim	V	1323	5 mm
Spare	185/60 R14	82H	Goodyear	Efficient	V	1223	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P0130:00/00304:000	O2 SENSOR CIRC.,BANK1-SENSOR 1 MALFUNCTION	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Engine bay dirty.

Electrical Components and Instruments: Radio needs authentication code to operate.

Body • Exterior: Dents and scratches on some body panels.Stone chips and spray work on some body panels.Some body panels misaligned.Poor residual traces of repair on some body panels

Undercarriage: Vehicle undercarriage dirty

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026

Car				Car			
Make/Model	VW Polo	Year	2017	Make/Model	VW Polo	Year	2017
Engine	1.6	Power	110 kW	Engine	1.6	Power	110 kW
Transmission	Manual	Gears	5	Transmission	Manual	Gears	5
Color	Grey	Color	Grey	Color	Grey	Color	Grey
VIN	AAVZZZ6RZPU015771						
Inspection results				Inspection results			
Brake	OK	Shock absorber	OK	Brake	OK	Shock absorber	OK
Steering	OK	Wheels	OK	Steering	OK	Wheels	OK
Light	OK	Exhaust	OK	Light	OK	Exhaust	OK
Body	OK	Interior	OK	Body	OK	Interior	OK
Engine	OK	Transmission	OK	Engine	OK	Transmission	OK
Electrical	OK	Other	OK	Electrical	OK	Other	OK

Brake and shock absorber repor

	Volkswagen Group of America Volkswagen of America, Inc. Volkswagen Financial Services Volkswagen Commercial Vehicles Volkswagen Leasing Volkswagen Insurance Volkswagen Credit Volkswagen Leasing Volkswagen Insurance Volkswagen Credit	Volkswagen Group of America Volkswagen of America, Inc. Volkswagen Financial Services Volkswagen Commercial Vehicles Volkswagen Leasing Volkswagen Insurance Volkswagen Credit Volkswagen Leasing Volkswagen Insurance Volkswagen Credit
Volkswagen VEHICLE DIAGNOSTIC REPORT		
Vehicle Make/Model: Volkswagen Polo		
Engine: 1.6	Power: 110 kW	Year: 2017
Transmission: Manual	Gears: 5	Color: Grey
VIN: AAVZZZ6RZPU015771	Diagnostic results	
Brake: OK	Shock absorber: OK	Wheels: OK
Steering: OK	Light: OK	Exhaust: OK
Body: OK	Interior: OK	Engine: OK
Electrical: OK	Transmission: OK	Other: OK

Diagnostic report page 1

Volkswagen VEHICLE DIAGNOSTIC REPORT			
Vehicle Information		Diagnostic Summary	
Vehicle Make/Model	VW Polo	Year	2017
Engine	1.6	Power	110 kW
Transmission	Manual	Gears	5
Color	Grey	Color	Grey
VIN	AAVZZZ6RZPU015771		
Diagnostic results			
Brake	OK	Shock absorber	OK
Steering	OK	Wheels	OK
Light	OK	Exhaust	OK
Body	OK	Interior	OK
Engine	OK	Transmission	OK
Electrical	OK	Other	OK

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771




CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Front bumper stiffener

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026



Oil cap and dipstick



Central Air Vent



Central Air Vent



Central Air Vent



Gear Selections



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771



CONDITION REPORT




Report No:
2017138036
DATE
27/01/2026



Windscreen



Radio/CD/USB



Front Fender Right



Door Front Right



Rear Fender Right



Fuel Flap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026



Rear bumper




Rear bumper



Rear bumper



Parcel Tray



Rear Fender Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026



Door Front Left



Tail Light Left



Tail Light Left



Front Fender Left



Bonnet



Air Conditioner

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026

Brake test			
	Brake force	Height	Efficiency
Front axle	2,35 kN	3,11 kN	20 %
Parking brake	0,23 kN	1,05 kN	75 %
Rear axle	0,73 kN	1,30 kN	56 %
Final evaluation state			
Deceleration service brake	22 %		
Deceleration parking brake	18 %		
		Total weight	1134 kg

Parking Brake Performance

Brake test			
	Brake force	Height	Efficiency
Front axle	2,45 kN	3,11 kN	20 %
Parking brake	0,23 kN	1,05 kN	75 %
Rear axle	0,73 kN	1,30 kN	56 %
Final evaluation state			
Deceleration service brake	22 %		
Deceleration parking brake	18 %		
		Total weight	1134 kg

Service Brake Performance Rear Axle



Front Bumper



Front Bumper



Rim Front Left



Sill Panel Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026



Radiator Cradle



Tyre Front Left



Engine



Tyre Rear Left



Chassis



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771



CONDITION REPORT



Report No:
2017138036
DATE
27/01/2026



Headlight Right



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6RZPU015771