



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	18/12/2023		M57 Pretoria Road - 1619
Inspection Date	18/12/2023		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	HM30RFGP
Model	POLO VIVO	Register Number	
VIN	AAVZZZ6SZEU022520	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	18/12/2023
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	292,163 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Hoses Damaged	Replace
Radiator Defective	Replace
Central Air Vent Damaged	Replace
Center Console / Cubbyhole + Lid Defective	Repair
Interior Lights Malfunction	Repair
Headlight Left Defective	Replace
Headlight Right Defective	Replace
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Defective	Repair
Seat Belt Rear Middle Defective	Repair
Hood Lining Dirty	Repair
Boot Carpet Defective	Repair
Mirror Adjusters Defective	Replace
Steering Wheel Trim Defective	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
C • Pillar Left Dented	Repair
Front Fender Left Dented	Repair
Front Fender Right Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Dented	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Damaged	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZ6SZEU022520

1 / 18



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

Damage	Repair Way
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Left Dented	Repair
Rocker Panel Left Dented	Repair
Rocker Panel Right Dented	Repair
Windscreen Cracked	Replace
Steering Rack Boot Left Damaged	Replace
Shock Absorber Front Right Damaged	Replace
Control Arm(s) Front Axle Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Damaged	
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Damaged	Replace
Chassis Dented	Repair
Sub Frame Scratched	Repair
Engine to silencer pipe Defective	Repair
Belly plates Damaged	Replace
Gearbox Oil Sweat	Repair
CV Joint(s) Front Left (inner/outer) Defective	Repair
CV Joint(s) Front Right (inner/outer) Defective	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Warning lights illuminated on dashboard	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.71	2.45	-	
Rear	1.99	1.97	-	
Emergency / Parking	0.87	1.42	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65 R14	82T	Eurovis	Roadstone	V	0322	4 mm
Front Right	175/65 R14	82T	Eurovis	Roadstone	V	0222	4 mm
Rear Left	185/60 R14	82H	Sumitomo	HTR	V	4620	0 mm
Rear Right	185/60 R14	82H	Sumitomo	HTR	V	4620	2 mm
Spare	175/65 R14	86T	RoadX	Rxmotion	V	3819	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	03-BRAKES 1	00285:008	RIGHT FRONT ABS WHEEL SPEED SENSOR-IMPLAUSIBLE SIG	

Inspection Conditions

No Test Drive
 Battery Flat
 Engine number – not possible to verify engine number (not visible without dismantling)
 Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: VEHICLE HAS NO LICENSE DISC
 Engine Compartment: Computer box strapped with cable ties. Engine bay dirty. Brake fluid level ok. Oil pan dented. Rust inside expansion bottle.
 Electrical Components and Instruments: Hooter not working.
 Lights: Left number plate light not working Front left dim light not working.
 Interior: Vehicle interior dirty and some interior panels scratched. Boot sealing rubber damaged.
 Body • Exterior: Dents and scratches on some body panels. Spray work on some body panels. Some body panels misaligned. Stone chips on some body panels.
 Signs of impact impact damage to front of vehicle.

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

**CONDITION REPORT**

VIN: AANZ76951620490

Report No: 201620490

2 / 18

DATE

18/12/2023

Axle and Suspension: Abnormal noise coming from front and rear suspension.

Tyres and Rims: Alloy rims scratched Loose second tyre inside boot of vehicle. Front and rear tyre sizes different. Front left and rear right wheel caps missing.

Undercarriage: Vehicle undercarriage dirty. Center exhaust bracket dented. Exhaust heat shields damaged.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT


Report No: 2016204900

VIN: AAVZZZ6SZEU022520


DATE 3/18 18/12/2023



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
VIN: AAVZZZ65751092023
18/10/2023
4 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

VIN: AAVZZZ6SZEU022520

5 / 18



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

VIN: AAVZZZ6SZEU022520

6 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za




CONDITION REPORT

Report No: 2016204900


DATE
18/12/2023

VIN: AAVZZZ6SZEU022520


7 / 18



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel and Accessories



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

VIN: AAVZZZ6SZEU022520

8 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick



Manual Transmission

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

VIN: AAVZZZ6SZEU022520

10 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

VIN: AAVZZZ6SZEU022520

12 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023



Headlight Right



Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

VIN: AAVZZZ6SZEU022520

14 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023



Rear bumper



Rear Fender Right

VIN: AAVZZZ6SZEU022520

15 / 18



Door Rear Right



Door Front Right



Front Fender Right



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

VIN: AAVZZZ6SZEU022520

16 / 18


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023



Seat Front Right




Seat Belt Rear Middle

VIN: AAVZZZ6SZEU022520
17 / 18



Seat Rear



Seat Rear



C • Pillar Left



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

VIN: AAVZZZ6SZEU022520

18 / 18

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023



Sill Panel Left



Central Air Vent



Engine



Hoses



Boot Carpet



Boot Carpet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023



Control Arm Bush(es) Front Axle Right



Tyre Rear Right



Control Arm Bush(es) Front Axle Left



Rocker Panel Left



Rocker Panel Right



CV Joint(s) Front Left (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023



CV Joint(s) Front Right (inner/outer)



Engine to silencer pipe



Gearbox



Chassis



Tyre Rear Left



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023



Inner Boot Floor Pan and Spare Wheel Well



CV Joint(s) Boot(s) Front Left (inner/outer)



Steering Rack Boot Left



Shock Absorber Front Right



Sub Frame



Control Arm(s) Front Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023



Engine



Radiator



Water level



Engine Wiring



Interior Lights



Center Console / Cubbyhole + Lid

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za





CONDITION REPORT

Report No: 2016204900

DATE
18/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za