



CONDITION REPORT

Report No: 2016204981

DATE
18/12/2023

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572

**Assignment**

Client	MFC Auction House	Inspection Location	MFC
Requested Date	18/12/2023		M57 Pretoria Road - 1619
Inspection Date	18/12/2023		Kempton Park - GT


Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	NB10655
Model	POLO VIVO	Register Number	
VIN	AAVZZZ6SZHU033010	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/12/2018
Color	GOLDEN	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	228,322 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories**Items**

VEHICLE INSPECTION

Damage	Repair Way
Engine Wiring Defective	Repair
Tail Light Right Cracked	Replace
Side Mirror Left Cracked	Repair
Front Bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Radiator Cradle Missing	Replace
Airbag light on	Repair





CONDITION REPORT

Report No: 2016204981

DATE
18/12/2023**Brakes****Brake Test Results**

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [kN]	Braking Force [kN]		
Front	2.3	2.1	-	
Rear	1.1	1.2	-	
Emergency / Parking	1.4	1.4	-	

Tyres and Rims**Tyre Specification & Measurement**

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R14	82H	Continental	Contact	V	1622	3 mm
Front Right	175/70R14	84H	Dunlop	Sp sport	V	4516	2 mm
Rear Left	175/65R14	82T	Continental	Contact	V	0920	2 mm
Rear Right	185/60R14	82H	Continental	Contact	V	0921	3 mm
Spare	185/60R14	82H	Continental	Contact	V	////	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

- No Test Drive
- Rain at time of inspection
- Battery Flat
- Engine number – not possible to verify engine number (not visible without dismantling)
- Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.
 Body • Exterior: Vehicle got minor scratches, stone chips and dents on some body panels

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT


VIN: AAV772652100001

Report No: 2016204981

2 / 8

DATE


18/12/2023



Shock and brake report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



CONDITION REPORT

Report No: 2016204981

VIN: AAVZZZ6SZHU033010

DATE

18/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204981

DATE

VIN: AAVZZZ6S78J02023

4 / 8



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



CONDITION REPORT

Report No: 2016204981

DATE

18/12/2023

VIN: AAVZZZ6SZHU033010

5 / 8

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016204981

DATE
18/12/2023

VIN: AAVZZZ6SZHU033010

6 / 8




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel fitted



LICENSE DISC



CONDITION REPORT

Report No: 2016204981

DATE
18/12/2023

VIN: AAVZZZ6SZHU033010

7 / 8



CONDITION REPORT

Report No: 2016204981

DATE
18/12/2023



CONDITION REPORT

Report No: 2016204981

DATE
18/12/2023



CONDITION REPORT

Report No: 2016204981

DATE
18/12/2023

Oil cap and dipstick



Windscreen



Water level



Front Bumper



Side Mirror Left



Tail Light Right



CONDITION REPORT

Report No: 2016204981

DATE
18/12/2023



CONDITION REPORT

Report No: 2016204981

DATE
18/12/2023

Engine Wiring



Radiator Cradle



Radiator Cradle



CONDITION REPORT

Report No: 2016204981

DATE
18/12/2023

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za