



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	10/09/2026		M57 Pretoria Road - 1619
Inspection Date	10/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	LY45SDGP
Model	POLO 2.0 TSI 147KW GTI 5-DR DSG [2023-2025]	Register Number	
		Date Of First Licensing	
VIN	AAVZZZAW4RU106838	Last COR	
Engine Number		License Expiry Date	30/09/2026
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2024	Fuel	PETROL
Km Reading	62,890 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AAVZZZAW4RU106838



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026



Damage	Repair Way
--------	------------

Center Console / Cubbyhole + Lid Missing	Replace
Switch Electrical Window Winder front left Damaged	Replace
Tail Light Left Cracked	Replace
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Dented	Repair
Door Front Left Damaged	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Damaged	Repair
Windscreen Cracked	Replace
Tyre Front Left Damaged	Replace
Rim Front Left Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Rim Spare Wheel Dented	Repair
Belly plates Damaged	Replace
Engine Noise Excessive	Repair
Front and rear tyre sizes different	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.81	4.24	-	
Rear	2.84	2.98	-	
Emergency / Parking	1.82	2.14	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/40Z R18	92W	Autogrip	P308	V	2324	2 mm
Front Right	225/40Z R18	92W	Autogrip	P308	V	2324	2 mm
Rear Left	215/40 R18	89V	Michelin	Pilot	V	2621	1 mm
Rear Right	215/40Z R18	89W	Fronway	Eurus	V	0523	2 mm
Spare	T125/60 R18	94M	Linglong	Temporary	V	4123	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAW4RU106838



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	01-ENGINE CONTROL MODULE 1	P305400	STARTER DOES NOT TURN MECHANICALLY BLOCKED OR ELEC	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels. Signs of impact damage to front of vehicle. Undercarriage: Bottom of engine and gearbox fully covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAW4RU106838



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026

Car		Licence		Licence	
State/Cat.	Car	License pl. no.	1345504	License	1345504
Make/Model	Volkswagen	Make/Model	VW Polo	License	1345504
Year	2014	Year	2014	License	1345504
Engine	1.6	Engine	1.6	License	1345504
Power	115 kW	Power	115 kW	License	1345504
Weight	1320 kg	Weight	1320 kg	License	1345504
Max. speed	185 km/h	Max. speed	185 km/h	License	1345504
Brake	Disc	Brake	Disc	License	1345504
Shock absorber	Disc	Shock absorber	Disc	License	1345504
Steering	Steering	Steering	Steering	License	1345504
Wheels	Wheels	Wheels	Wheels	License	1345504
Tires	Tires	Tires	Tires	License	1345504
Lighting	Lighting	Lighting	Lighting	License	1345504
Electrical	Electrical	Electrical	Electrical	License	1345504
Exhaust	Exhaust	Exhaust	Exhaust	License	1345504
Other	Other	Other	Other	License	1345504

Brake and shock absorber report

Vehicle		Engine		Transmission	
Make/Model	VW Polo	Make/Model	VW Polo	Make/Model	VW Polo
Year	2014	Year	2014	Year	2014
Engine	1.6	Engine	1.6	Engine	1.6
Power	115 kW	Power	115 kW	Power	115 kW
Weight	1320 kg	Weight	1320 kg	Weight	1320 kg
Max. speed	185 km/h	Max. speed	185 km/h	Max. speed	185 km/h
Brake	Disc	Brake	Disc	Brake	Disc
Shock absorber	Disc	Shock absorber	Disc	Shock absorber	Disc
Steering	Steering	Steering	Steering	Steering	Steering
Wheels	Wheels	Wheels	Wheels	Wheels	Wheels
Tires	Tires	Tires	Tires	Tires	Tires
Lighting	Lighting	Lighting	Lighting	Lighting	Lighting
Electrical	Electrical	Electrical	Electrical	Electrical	Electrical
Exhaust	Exhaust	Exhaust	Exhaust	Exhaust	Exhaust
Other	Other	Other	Other	Other	Other

Diagnostic report page 1

Vehicle		Engine		Transmission	
Make/Model	VW Polo	Make/Model	VW Polo	Make/Model	VW Polo
Year	2014	Year	2014	Year	2014
Engine	1.6	Engine	1.6	Engine	1.6
Power	115 kW	Power	115 kW	Power	115 kW
Weight	1320 kg	Weight	1320 kg	Weight	1320 kg
Max. speed	185 km/h	Max. speed	185 km/h	Max. speed	185 km/h
Brake	Disc	Brake	Disc	Brake	Disc
Shock absorber	Disc	Shock absorber	Disc	Shock absorber	Disc
Steering	Steering	Steering	Steering	Steering	Steering
Wheels	Wheels	Wheels	Wheels	Wheels	Wheels
Tires	Tires	Tires	Tires	Tires	Tires
Lighting	Lighting	Lighting	Lighting	Lighting	Lighting
Electrical	Electrical	Electrical	Electrical	Electrical	Electrical
Exhaust	Exhaust	Exhaust	Exhaust	Exhaust	Exhaust
Other	Other	Other	Other	Other	Other

Diagnostic report page 2

Vehicle		Engine		Transmission	
Make/Model	VW Polo	Make/Model	VW Polo	Make/Model	VW Polo
Year	2014	Year	2014	Year	2014
Engine	1.6	Engine	1.6	Engine	1.6
Power	115 kW	Power	115 kW	Power	115 kW
Weight	1320 kg	Weight	1320 kg	Weight	1320 kg
Max. speed	185 km/h	Max. speed	185 km/h	Max. speed	185 km/h
Brake	Disc	Brake	Disc	Brake	Disc
Shock absorber	Disc	Shock absorber	Disc	Shock absorber	Disc
Steering	Steering	Steering	Steering	Steering	Steering
Wheels	Wheels	Wheels	Wheels	Wheels	Wheels
Tires	Tires	Tires	Tires	Tires	Tires
Lighting	Lighting	Lighting	Lighting	Lighting	Lighting
Electrical	Electrical	Electrical	Electrical	Electrical	Electrical
Exhaust	Exhaust	Exhaust	Exhaust	Exhaust	Exhaust
Other	Other	Other	Other	Other	Other

Diagnostic report page 3

Vehicle		Engine		Transmission	
Make/Model	VW Polo	Make/Model	VW Polo	Make/Model	VW Polo
Year	2014	Year	2014	Year	2014
Engine	1.6	Engine	1.6	Engine	1.6
Power	115 kW	Power	115 kW	Power	115 kW
Weight	1320 kg	Weight	1320 kg	Weight	1320 kg
Max. speed	185 km/h	Max. speed	185 km/h	Max. speed	185 km/h
Brake	Disc	Brake	Disc	Brake	Disc
Shock absorber	Disc	Shock absorber	Disc	Shock absorber	Disc
Steering	Steering	Steering	Steering	Steering	Steering
Wheels	Wheels	Wheels	Wheels	Wheels	Wheels
Tires	Tires	Tires	Tires	Tires	Tires
Lighting	Lighting	Lighting	Lighting	Lighting	Lighting
Electrical	Electrical	Electrical	Electrical	Electrical	Electrical
Exhaust	Exhaust	Exhaust	Exhaust	Exhaust	Exhaust
Other	Other	Other	Other	Other	Other

Diagnostic report page 4

Vehicle		Engine		Transmission	
Make/Model	VW Polo	Make/Model	VW Polo	Make/Model	VW Polo
Year	2014	Year	2014	Year	2014
Engine	1.6	Engine	1.6	Engine	1.6
Power	115 kW	Power	115 kW	Power	115 kW
Weight	1320 kg	Weight	1320 kg	Weight	1320 kg
Max. speed	185 km/h	Max. speed	185 km/h	Max. speed	185 km/h
Brake	Disc	Brake	Disc	Brake	Disc
Shock absorber	Disc	Shock absorber	Disc	Shock absorber	Disc
Steering	Steering	Steering	Steering	Steering	Steering
Wheels	Wheels	Wheels	Wheels	Wheels	Wheels
Tires	Tires	Tires	Tires	Tires	Tires
Lighting	Lighting	Lighting	Lighting	Lighting	Lighting
Electrical	Electrical	Electrical	Electrical	Electrical	Electrical
Exhaust	Exhaust	Exhaust	Exhaust	Exhaust	Exhaust
Other	Other	Other	Other	Other	Other

Diagnostic report page 5

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAW4RU106838



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAW4RU106838



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AAVZZZAW4RU106838



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAW4RU106838



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026



Front chassis



Rear chassis



Oil cap and dipstick



Center Console / Cubbyhole + Lid



Front Fender Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAW4RU106838



CONDITION REPORT



Report No:


2017297167

DATE

10/09/2026



Door Front Right



Door Rear Right



Door Rear Right



Rear bumper



Rear bumper



Rim Spare Wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAW4RU106838



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026



Rear Fender Left



Door Rear Left



Door Front Left



Switch Electrical Window Winder front left



Side Mirror Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAW4RU106838



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026



Bonnet



Windscreen



Tail Light Left



Water level



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAW4RU106838



CONDITION REPORT




Report No:
2017297167
DATE
10/09/2026



Front Bumper



Tyre Front Left



Rim Front Left



Sill Panel Left



Sill Panel Left



Rim Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAW4RU106838



CONDITION REPORT



Report No:
2017297167
DATE
10/09/2026



Rim Rear Right



Belly plates



Belly plates



Belly plates



Belly plates



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAW4RU106838