



## CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 14/12/2023        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 14/12/2023        |                     | Kempton Park - GT        |

## Vehicle Data

|                 |                    |                         |            |
|-----------------|--------------------|-------------------------|------------|
| Vehicle Type    | LIGHT LOAD VEHICLE | Registered Owner        | MFC        |
| Manufacturer    | FORD               | Registration Number     | NJ101361   |
| Model           | RANGER             | Register Number         |            |
| VIN             | AFAPXXMJ2PFJ19126  | Date Of First Licensing |            |
| Engine Number   |                    | Last COR                |            |
| Doors           | 4                  | License Expiry Date     | 14/12/2023 |
| Color           | WHITE              | Power / Displacement    |            |
| Year Model      |                    | Paint Finish            | C - COMMON |
| Km Reading      | 151,350 KM         | Fuel                    | DIESEL     |
| Cab / Body Type | DOUBLE CAB         | Transmission            | MANUAL     |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

| Damage                                | Repair Way |
|---------------------------------------|------------|
| Air conditioner pump Damaged          | Replace    |
| Alternator Damaged                    | Replace    |
| Fog Light Front Left Damaged          | Replace    |
| Seat Front Right Torn / Cut           | Repair     |
| Door Panel Rear Right Missing         | Replace    |
| Door Handle Front Left Missing        | Replace    |
| Side Mirror Left Damaged              | Replace    |
| Front Bumper Paintwork • Scratched    | Repair     |
| Door Front Left Paintwork • Scratched | Repair     |
| Door Rear Left Paintwork • Scratched  | Repair     |
| Roof Paintwork • Flaking              | Repair     |
| Tyre Front Left Torn / Cut            | Replace    |
| Gearbox Oil Sweat                     | Repair     |

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AFAPXXMJ2PFJ19126

1 / 10



## CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

### Brakes

#### Brake Test Results

No Brake Test on a brake test machine has been performed.  
Brake efficiency tested during road test.

|                     | Left               | Right              |                  |                                  |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
| Front               | -                  | -                  | -                |                                  |
| Rear                | -                  | -                  | -                |                                  |
| Emergency / Parking | -                  | -                  | -                |                                  |

### Tyres and Rims

#### Tyre Specification & Measurement

|             | Size      | Load/Speed Index | Manufacture | Model     | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|-----------|-------|-----------------|------------------|
| Front Left  | 305/60R18 | 121/118Q         | Cooper      | Discovery | V     | 0118            | 6 mm             |
| Front Right | 305/60R18 | 121/118Q         | Cooper      | Discovery | V     | 0118            | 7 mm             |
| Rear Left   | 305/60R18 | 121/118Q         | Cooper      | Discovery | V     | 5117            | 7 mm             |
| Rear Right  | 205/60R18 | 121/118Q         | Cooper      | Discovery | V     | 0218            | 7 mm             |
| Spare       | 265/60R18 | 110T             | Continental | Contact   | V     | ///////         | 7 mm             |

\* Tyre Legend: V=Virgin, R=Recap

### Diagnostic

A vehicle diagnostic has not been conducted.

### Inspection Conditions

No Test Drive  
Vehicle doesn't start  
Battery Flat  
Engine number – not possible to verify engine number (not visible without dismantling)  
Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.VEHICLE IS A NON RUNNING.NO BRAKE TEST PERFORMED.  
Engine Compartment: All pulley belts missing, vehicle is a non runner  
Electrical Components and Instruments: Electronics malfunction.  
Body • Exterior: Minor dents scratches and stone chips on some body panels. Signs of spray work done on some body panels.  
Undercarriage: Signs of surface rust on undercarriage.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



CONDITION REPORT

Report No: 2016202351


DATE  
14/12/2023



Diagnostic test



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AFAPXXMJ2PFJ19126  
3 / 10



CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AFAPXXMJ2PFJ19126  
4 / 10



## CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AFAPXXMJ2PFJ19126

5 / 10



CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AFAPXXMJ2PFJ19126  
6 / 10



## CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel



LICENSE DISC



CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AFAPXXMJ2PFJ19126  
8 / 10



## CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Rear chassis



Manual



CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: AFAPXXMJ2PFJ19126  
10 / 10



## CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

Expansion bottle



Oil cap and dipstick



Warning light illuminated.



Door Handle Front Left



Door Panel Rear Right



Seat Front Right



CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



## CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

Water level



Alternator



Alternator



Air conditioner pump



Roof



Front Bumper



CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za



## CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

Front Bumper



Front Bumper



Fog Light Front Left



Tyre Front Left



Door Front Left



Door Rear Left



CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za




## CONDITION REPORT

Report No: 2016202351

DATE  
14/12/2023

Gearbox



Gearbox



Side Mirror Left

**CONDITION REPORT****Report No: 2016202351****DATE**  
**14/12/2023**

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)