



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	09/09/2026		M57 Pretoria Road - 1619
Inspection Date	09/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	HFG367L
Model	HI-ACE 2.5 SESFIKILE 16-S DSL MINIBUS [2021-2024]	Register Number	
		Date Of First Licensing	
VIN	AHTSS22P507151225	Last COR	
Engine Number		License Expiry Date	30/09/2026
Doors	4	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2023	Fuel	DIESEL
Km Reading	164,838 KM	Transmission	MANUAL
Cab / Body Type	STATION WAGON		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:

2017296263

DATE

09/09/2026

Damage

Repair Way

Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Expansion Bottle Damaged	Replace
Alternator Defective	Replace
Air cleaner Damaged	Replace
Under bonnet insulation cover Damaged	Repair
Central Air Vent Damaged	Replace
Radio/CD/USB Defective	Repair
Windscreen Wiper Damaged	Replace
Fog Light Front Right Missing	Replace
Seat Front Left Damaged	Repair
Seat Rear Damaged	Repair
Sun Visor Left Damaged	Replace
Sun Visor Right Damaged	Replace
Hood Lining Damaged	Repair
Dash Padding Damaged	Repair
Carpet Rear Damaged	Repair
Steering Wheel Trim Defective	Repair
Front Bumper Damaged	Repair
Grill Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Repair
Front Fender Right / Inner Tray Damaged	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Rear Fender Right / Inner Tray Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Damaged	Repair
Door Rear Left Paintwork • Scratched	Repair
Weather Strip Door Front Right Damaged	Replace
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Roof Dented	Repair
Windscreen Cracked	Replace
Caliper 1. Axle left Damaged	Replace
Caliper 1. Axle right Damaged	Replace
Brake Drum 2. Axle right Damaged	Replace
Speed Sensor Damaged	Replace
Service Brake Performance Front Axle Left / Right	Repair
Difference out of legal range	
Stabilizer Mounting Front Right Damaged	Replace
Control Arm(s) Front Axle Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Rim Front Left Damaged	Repair
Chassis Damaged	Repair
Sub Frame Damaged	Replace
Engine to silencer pipe Welded	Replace
Catalytic converter Missing	Replace
Fuel Tank Dented	Repair
Riding Height Front Incorrect	Repair
Radiator Cradle Damaged	Replace
Triangle Missing	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026

Damage	Repair Way
Loose sound wiring inside of vehicle	Replace
Warning lights illuminated on dashboard	Repair
Interior boot panel damaged	Repair
Rear right interior panel damaged	Repair
Rear left window net missing	Replace
Rear left door step box loose	Repair
Deceleration service brake defective	Repair
Rear right shock absorber weak	Replace
Engine oil sump damaged	Replace
Spare Wheel missing	Replace
Loose wiring on undercarriage	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	5.59	4.0	-	
Rear	1.22	0.99	-	
Emergency / Parking	2.08	3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/75R14C	109R	Powertrac	VanMarch	V	3925	3 mm
Front Right	205/75R14C	109R	Powertrac	VanMarch	V	3925	2 mm
Rear Left	205/75R14C	109R	Powertrac	VanMarch	V	3024	0 mm
Rear Right	205/75R14C	109R	Powertrac	VanMarch	V	3525	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Alternator pulley welded.
Electrical Components and Instruments: Radio not working.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:

2017296263

DATE

09/09/2026

Interior: Vehicle interior dirty and panels scratched. Interior A pillar plastic trims defective. Aftermarket sound fitted to vehicle.
Body • Exterior: Dents and scratches on body panels. Nudge bar dented.
Brakes: Front left and right brake calipers grinded down to fit smaller rim. Rear left speed sensor damaged.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:


2017296263

DATE _____

09/09/2026

[illegible]

Brake and shock absorber report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:

2017296263

DATE

09/09/2026




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel Accessories



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:

2017296263

DATE


09/09/2026




VIN PLATE OR STICKER



ENGINE 1




Front chassis



Rear chassis



Loose wiring on undercarriage



Engine oil sump

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Loose wiring



Oil cap and dipstick



Rear right interior panel



Interior boot panel



Boot Lid / Hatch door



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Rear bumper



Rear bumper



Bonnet



Bonnet



Expansion Bottle



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Windscreen



Windscreen Wiper



Sun Visor Left



Sun Visor Right



Hood Lining



Central Air Vent

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Dash Padding



Steering Wheel Trim



Weather Strip Door Front Right



Front Fender Right / Inner Tray



Rear Fender Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Door Front Right



Fog Light Front Right



Grill



Grill



Door Front Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Door Rear Left



Door Rear Left



Rear Fender Left



Rear Fender Left



Seat Front Left



Front Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Seat Rear



Seat Rear



Seat Rear



Carpet Rear



Rear Fender Left / Inner Tray



Rear Fender Right / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:

2017296263

DATE

09/09/2026



Rear Fender Right



Radio/CD/USB

Brake test			
	Brake force		
	left	right	Difference
Front axle	5.52 kN	4.00 kN	28 %
Parking brake	2.05 kN	3.00 kN	31 %
Rear axle	1.33 kN	0.95 kN	19 %
Final evaluation status		48 %	
Transmission service brake		21 %	
Deceleration parking brake			
Total weight:			2489 kg

Service Brake Performance Front Axle



Engine Wiring



Sill Panel Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Front Bumper



Front Bumper



Rim Front Left



Front Fender Left / Inner Tray



Sill Panel Left



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Tyre Rear Left



Tyre Rear Right



Tyre Rear Right



Radiator Cradle



Sub Frame



Sub Frame

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Sub Frame



Fuel Tank



Engine



Catalytic converter



Control Arm(s) Front Axle Right



Caliper 1. Axle left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Caliper 1. Axle right



Engine Wiring



Front Fender Left / Inner Tray



Front Fender Right / Inner Tray



Engine Wiring



Alternator

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Stabilizer Mounting Front Right



Air cleaner



Front Fender Right / Inner Tray



Brake Drum 2. Axle right



Speed Sensor



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Chassis



Chassis



Riding Height Front



Riding Height Front



Under bonnet insulation cover



Hood Lining

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225



CONDITION REPORT



Report No:
2017296263
DATE
09/09/2026



Roof



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AHTSS22P507151225