

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--
 VIN: AHTSS22P007150256

Odometer Reading: 21761km
 License Plate: LG96ZXGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V9.10

Serial Number: VB8GJCC01482
 Repair Order Number: --

System Scanned(5)

System	Status/DTC
Engine and ECT	2
ABS/VSC/TRC	4
SRS airbag	3
Combination meter	3
Immobilizer	0

DTC (12)

Engine and ECT (2 DTCs)

DTC	Description	Status
P0504	Brake switch A/B correlation	History
P2138	Throttle/pedal position sensor/switch D/E voltage correlation	History

ABS/VSC/TRC (4 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1433	Steering angle sensor (SAS) internal circuit	Current
C1433	Steering angle sensor (SAS) internal circuit	History
U0126	Lost communication with steering angle sensor (SAS) module	History

SRS airbag (3 DTCs)

DTC	Description	Status
B1801	Driving side squib circuit open	Current
B1801	Driving side squib circuit open	History

B1806	P squib circuit open	History
-------	----------------------	---------

Combination meter (3 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History
U0129	Lost communication with brake system control module	History
B1507	Turn signal circuit open	History

Technician Notes

2016217559

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.