

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(BI3)/--
VIN: MALBG512LNM060666

Odometer Reading: 182178KM
License Plate: KB11VVGp

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (13)

System	Status/DTC
ENG (Engine)	 3
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 0
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
AVN (Audio Video Navigation)	  0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 0
RVM (Rear View Monitor)	  0

DTC (3)

ENG (Engine) (3 DTCs)

DTC	Description	Status
P000A:00	Camshaft position (CMP) A slow response (Bank 1)	History

P0011:00	Intake camshaft position (CMP) A timing over-Advanced or system performance (Bank 1)	History
P0016:00	Crankshaft position (CKP) - Camshaft position (CMP) correlation (Bank 1 sensor A (intake))	Active

Technician Notes
2017295814

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.