

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/CRETA(SU2i)/ALCAZAR(PS7i)/G 2.0 MPI NU PE
VIN: MALPC815LPM830541

Odometer Reading: 207130KM
License Plate: KX52MMGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (14)

System	Status/DTC
ENG (Engine)	 1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 3
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 7
A/C (Air Conditioner)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 7
WPC (Wireless Power Charger)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 7
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 7
ICU (Integrated Central Control Unit)	 3
RVM (Rear View Monitor)	  0

DTC (35)

ENG (Engine) (1 DTC)

DTC	Description	Status
P2504:00	Charging system voltage high	Active

AB (Airbag) (3 DTCs)

DTC	Description	Status
B2613:00	Airbag control unit (ACU) airbag warning lamp CAN message error	History
B2617:00	Cluster airbag warning lamp CAN message timeout	History
B2618:00	Cluster airbag warning lamp CAN message timeout by CAN bus	History

IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System) (7 DTCs)

DTC	Description	Status
B1214:00	Left rear sensor fault	Active
B1215:00	Rear center left sensor fault	Active
B1216:00	Rear center right sensor fault	Active
B1217:00	Right rear sensor fault	Active
C1314:00	Left rear sensor radio frequency channel failure	Active
C1315:00	Right rear sensor radio frequency channel failure	Active
C1662:00	Auto learning failure	Active

IBU-BCM (Integrated Body Control Unit-Body Control Module) (7 DTCs)

DTC	Description	Status
B1214:00	Left rear sensor fault	Active
B1215:00	Rear center left sensor fault	Active
B1216:00	Rear center right sensor fault	Active
B1217:00	Right rear sensor fault	Active
C1314:00	Sensor 3 radio frequency channel failure	Active
C1315:00	Sensor 4 radio frequency channel failure	Active
C1662:00	Auto learning failure	Active

IBU-SMK (Integrated Body Control Unit-Smart Key Unit) (7 DTCs)

DTC	Description	Status
B1214:00	Left rear sensor fault	Active
B1215:00	Rear center left sensor fault	Active
B1216:00	Rear center right sensor fault	Active
B1217:00	Right rear sensor fault	Active
C1314:00	Sensor 3 radio frequency channel failure	Active
C1315:00	Sensor 4 radio frequency channel failure	Active
C1662:00	Auto learning failure	Active

IBU-IMMO (Integrated Body Control Unit-Immobilizer) (7 DTCs)

DTC	Description	Status
-----	-------------	--------

B1214:00	Left rear sensor fault	Active
B1215:00	Rear center left sensor fault	Active
B1216:00	Rear center right sensor fault	Active
B1217:00	Right rear sensor fault	Active
C1314:00	Sensor 3 radio frequency channel failure	Active
C1315:00	Sensor 4 radio frequency channel failure	Active
C1662:00	Auto learning failure	Active

ICU (Integrated Central Control Unit) (3 DTCs)

DTC	Description	Status
B251D:00	Right stop lamp circuit short to ground	History
B2525:00	Right rear turn signal lamp circuit short to ground	History
B258C:00	Right rear external tail lamp circuit short to ground	History

Technician Notes

2017292686

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.