

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Swift/--
VIN: MBHCZC63S00498646

Odometer Reading: 122804
License Plate: JL77TZGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	1
TCM(Transmission Control Module)	1
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	2
SRS(Airbag)	1
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	3
EPS(Power steering)	1
BCM(Body Control Module)	1
SMK(Immobilizer and/or keyless system)	1

DTC (11)

ECM/PCM(Engine/powertrain) (1 DTC)

DTC	Description	Status
U0121	Lost communication with ABS or electronic stability program control module	History

TCM(Transmission Control Module) (1 DTC)

DTC	Description	Status
U0121	Lost communication with ABS or electronic stability program control module	History

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1057	Power supply voltage	History
U0100	Lost communication with ECM	History

SRS(Airbag) (1 DTC)

DTC	Description	Status
B1004-18	Power source voltage too low	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (3 DTCs)

DTC	Description	Status
B1840	Vehicle speed data invalid	History
U0100	Lost communication with ECM	History
U0121	Lost communication with ABS or electronic stability program control module	History

EPS(Power steering) (1 DTC)

DTC	Description	Status
C1161	CAN invalid data from vehicle speed	History

BCM(Body Control Module) (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM	History

SMK(Immobilizer and/or keyless system) (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM	History

Technician Notes

2017295703

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.