

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/CLIO IV--
VIN: VF15RSV0A58010309

Odometer Reading: 200893km
License Plate: HD95NTGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
INJ(Injection)	 3
ABS(Anti-lock braking system)	 2
ABG(Airbag / pretensioners)	 2
TDB(Instrument panel)	 4
UCH(Central control unit)	 0
DAV(Variable power assist steering)	 1
RDO(Radio)	  4
CLI(Air conditioning)	 1
HFM(Hands-free module)	 3

DTC (20)

INJ(Injection) (3 DTCs)

DTC	Description	Status
DTC001177	Inlet camshaft shifter Assistance fault	Active
DTC0226F1	Accelerator pedal position Jammed accelerator pedal detected.	Memory
DTC056016	Computer supply voltage Permanent low level	Memory

ABS(Anti-lock braking system) (2 DTCs)

DTC	Description	Status
DTCC40100	Invalid INJ. Multiplex signals	Memory
DTCF00316	Computer power supply Circuit voltage below threshold	Memory

ABG(Airbag / pretensioners) (2 DTCs)

DTC	Description	Status
DTCF00316	Computer supply voltage Feed voltage too low	Memory
DTCF00317	Computer supply voltage Feed voltage too high	Memory

TDB(Instrument panel) (4 DTCs)

DTC	Description	Status
DTC94011C	Oil level sensor circuit Battery voltage outside range	Memory
DTC941211	External temperature sensor circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory

DAV(Variable power assist steering) (1 DTC)

DTC	Description	Status
DTCF00317	Computer power supply Excess voltage	Memory

RDO(Radio) (4 DTCs)

DTC	Description	Status
DTC931513	FM1 receiver Open circuit	Memory
DTC932813	Microphone Open circuit	Memory
DTC934149	Computer configuration Internal electronic fault	Memory
DTC93CF73	Key jammed Internal electronic fault	Memory

CLI(Air conditioning) (1 DTC)

DTC	Description	Status
DTCF00316	Computer supply voltage Low voltage	Memory

HFM(Hands-free module) (3 DTCs)

DTC	Description	Status
DTCA05111	VER(Steering lock) Short circuit to earth.	Memory

DTCA05177	VER(Steering lock) Control position inaccessible	Memory
DTCA06004	Wake up signal Internal fault	Memory

Technician Notes
2017296281

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.