

Opel VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Opel/Corsa F--

VIN: VXKUPHMGBN4239550

Odometer Reading: 75232km

License Plate: LBR738NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Version: V9.20

Serial Number: VB8GJCC01509

Repair Order Number: --



System Scanned (17)

System	Status/DTC
Built-in Systems Interface (BSI) -- BSI2010_EV	17
Engine ECU -- CMM_V56	0
ABS or ESP -- ESPMK100_UDS	3
Airbags and pretensioners ECU -- RBG_SPEED_UDS	1
Combination instrument -- COMBINE_UDS	0
Parking assist -- AAS_UDS_G6	4
A/C -- BCC	0
Power steering -- DAE_UDS	0
Battery State Of Charge (SOC) control unit -- BECB_GEN2	0
Controls under the steering wheel -- COM2016	0
Steering wheel controls / Integral controls steering wheel -- VCI	1
Multi-function control panel -- FMUX	0
Seatbelt not fastened warning lamps unit -- TNB_2010	0
Multi-function video camera (CMF) -- CVM_3	1
Touchscreen -- EMF_DGT_UDS_GP	2
Radio navigation system/connected audio system remote control (only for 7-inch screen) -- CRT_A	0
Radio navigation or telematic unit (RTx) -- RCC	5



DTC (34)

Built-in Systems Interface (BSI) – BSI2010_EV (17 DTCs)

DTC	Description	Status
U1F3B:87	No communication with multi-function control unit or the warning lamp for seatbelt not fastened	Intermittent
B2ED3:00	Loss of Built-in Systems Interface (BSI) time counter	Present
B1165:15	Fault in left brake lamp control -- Circuit open or short to positive	Intermittent
B1169:15	Fault in left rear turn lamp control -- Circuit open or short to positive	Intermittent
B1163:15	Fault in license plate lighting control -- Circuit open or short to positive	Intermittent
B11F0:48	Traceability of the forcing of the maintaining of the low beam headlamps switch-on : Ignore this fault -- Software fault	Intermittent
B162C:12	Accessories positive relay control and status inconsistent - - Relay not activated But Active	Intermittent
B133E:15	Rear window relay control output fault -- Circuit open or short to positive	Present
B133D:15	Front window relay control output fault -- Circuit open or short to positive	Present
B170C:11	Child lock or automatic high beam/low beam switch function activation button fault -- Key locked Or Short circuit to ground	Intermittent
B1718:62	Remote control unsynchronized	Intermittent
B1865:23	Inconsistency between status of engine starting switch and status of Built-in Systems Interface (BSI) engine starting authorization output	Intermittent
B1805:62	Starter fault -- Consistency	Intermittent
B1806:62	Cutting out engine when driving fault -- Consistency	Intermittent
B1418:00	Fault in seatbelt fastening information status for determining presence of driver	Intermittent
U1F1A:08	Fault in communication on LIN 1	Intermittent
B1003:00	Configuration fault (Warning! This may be a phantom fault)	Present

ABS or ESP – ESPMK100_UDS (3 DTCs)

DTC	Description	Status
C0031:68	Left front Wheel Speed Sensor (WSS) -- Operation not performed	Intermittent

C003A:68	Right rear Wheel Speed Sensor (WSS) -- Operation not performed	Intermittent
C0037:68	Left rear Wheel Speed Sensor (WSS) -- Operation not performed	Intermittent

Airbags and pretensioners ECU – RBG_SPEED_UDS (1 DTC)

DTC	Description	Status
B1400:64	CAN+ supply voltage -- Actuator present but not configured	Intermittent

Parking assist – AAS_UDS_G6 (4 DTCs)

DTC	Description	Status
B1223:14	Fault in inner left rear parking assistance sensor -- Circuit open or short to ground	Intermittent
B1224:14	Outer left rear parking assist sensor fault -- Circuit open or short to ground	Intermittent
B1227:14	Fault in inner right rear parking assistance sensor -- Circuit open or short to ground	Intermittent
B1228:14	Outer right rear parking assist sensor fault -- Circuit open or short to ground	Intermittent

Steering wheel controls / Integral controls steering wheel – VCI (1 DTC)

DTC	Description	Status
U1F1A:87	Fault in transmission by top-of-column on LIN -- Not characterized	Intermittent

Multi-function video camera (CMF) – CVM_3 (1 DTC)

DTC	Description	Status
B1238:00	Field of vision of the multi-function video camera -- Hindering object detected	Intermittent

Touchscreen – EMF_DGT_UDS_GP (2 DTCs)

DTC	Description	Status
B1574:1C	Please refer to vehicle service manual.	
U1FA0:00	Please refer to vehicle service manual.	

Radio navigation or telematic unit (RTx) – RCC (5 DTCs)

DTC	Description	Status
B100C:00	RCC connected audio system electrical supply -- Not characterized	Intermittent
B1517:04	RCC connected audio system (Bluetooth module) -- Internal fault	Intermittent
B1562:12	USB2 port (USB port used) -- Short circuit to positive	Intermittent
B1563:00	USB1 port (USB port used) -- Electrical fault	Intermittent

B1563:12

USB1 port (USB port used) -- Short circuit to positive

Intermittent

Technician Notes

2017293982

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.