

BMW VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/BMW/3'/328i_N20/--

VIN: WBA3A56000NR04154

Odometer Reading: 136407km

License Plate: JN48FSGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V19.10

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned (17)

System	Status/DTC
DME (Engine-Digital Motor Electronics)	3
EGS (Electronic Transmission Management)	0
DSC (Dynamic Stability Control)	2
ACSM (Airbag-Advanced Crash Safety Module)	2
KOMBI (Instrument Cluster)	0
FEM (Front Electronic Module)	9
ZGM (Central Gateway Module)	3
EKPS (Electric Fuel Pump Control)	0
ICM (Integrated Chassis Management)	0
EPS (Electric Power Steering)	0
CBX-MEDIA (ComBox Multimedia)	0
FZD (Roof Function Center)	3
GWS (Gear Selector Switch)	0
HUB (Headunit Basis)	0
CON (Controller)	1
REM (Rear Electronic Module)	3
IHKA (Integrated Automatic Heating And A/C System)	0

DTC (26)

DME (Engine-Digital Motor Electronics) (3 DTCs)

DTC	Description	Status
1D2404	Map thermostat, activation: line disconnection	Intermittent
213501	Power management: Total discharge	Intermittent
213901	Power management: Reduction or shutdown of individual electrical consumer	Intermittent

DSC (Dynamic Stability Control) (2 DTCs)

DTC	Description	Status
480AB7	DSC control unit: Slight undervoltage	Intermittent
480A11	Brake pad wear sensor: Front axle, replace brake pads	Permanent

ACSM (Airbag-Advanced Crash Safety Module) (2 DTCs)

DTC	Description	Status
930AA1	Crash safety module: Undervoltage	Intermittent
930AA3	Crash safety module: Undervoltage detected in self-test	Intermittent

FEM (Front Electronic Module) (9 DTCs)

DTC	Description	Status
804011	Undervoltage 8V5	Intermittent
804013	No supply voltage to Terminal 30L1	Intermittent
804014	No supply voltage to Terminal 30L2	Intermittent
8040B7	De-activation of terminal 15: Top startability limit reached	Intermittent
8040BD	Reset or deactivation of terminal 30F	Intermittent
8041A7	Headlight courtesy delay feature, repeat interlock, active	Intermittent
8041A8	Welcome light repeat lock active	Intermittent
8041BF	Rain-light-solar-condensation sensor: Light sensor, signal implausible	Intermittent
804415	Radio remote control: Battery undervoltage	Intermittent

ZGM (Central Gateway Module) (3 DTCs)

DTC	Description	Status
CD0420	ZGM, FlexRay controller signalling fault	Intermittent
CD0487	ZGM: Synchronisation process for FlexRay failed	Intermittent
801C20	ZGM: central fault memory full - no control-unit fault	Permanent

FZD (Roof Function Center) (3 DTCs)

DTC	Description	Status
-----	-------------	--------

801A4C	SINE: Undervoltage in the internal voltage supply detected	Intermittent
801A55	DWA: The alarm has been activated	Permanent
030220	SHD: Slide/tilt sunroof is not initialised	Intermittent

CON (Controller) (1 DTC)

DTC	Description	Status
801405	CON: Undervoltage	Intermittent

REM (Rear Electronic Module) (3 DTCs)

DTC	Description	Status
03019C	Window regulator, passenger's side door, rear: no initialisation of drive unit possible	Intermittent
804811	Undervoltage	Intermittent
804872	Brake light, left, faulty	Permanent

Technician Notes

2016278566

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.