

Mercedes-Benz VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mercedes-Benz/C (205)/--

VIN: WDD2050402R431828

Odometer Reading: 130370km

License Plate: KD69DYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V19.33

Repair Order Number: --



System Scanned (39)

System	Status/DTC
ECM(Engine Control Unit)	3
TCM(Transmission Control Unit)	6
ESP(Electronically controlled vehicle stability braking system control unit)	3
SRS(Supplemental Restraint System Control Unit)	0
KI(Instrument Cluster)	0
TPM(Tire Pressure Monitor Control Unit)	0
SAMF(Front SAM signal acquisition control unit)	3
LIN:BSN(Battery Sensor)	0
LIN:FSW(Wiper Motor)	0
LIN:VCS(Rain/sunlight sensor)	0
SAMR(Rear SAM signal acquisition control unit)	0
EZS(Electronic Ignition Lock Control Unit)	1
ES(Electric Power Steering)	1
KLA(Air Conditioner Control Unit)	1
PTCU(Drivetrain Control Unit)	0
HU(Head Unit Control Unit)	1
KG(Keyless Go Control Unit)	0
SW-SW-R(Right Headlamp Control Unit)	0
SW-SW-L(Left Headlamp Control Unit)	1
LRE(Steering Wheel Electronics)	0

ABA(Collision Prevention Assist)	ADAS	✓ 0
DMFL(Left Front Door Control Unit)		✓ 0
DMFR(Right Front Door Control Unit)		✗ 1
DMRR(Right Rear Door Control Unit)		✓ 0
DMRL(Left Rear Door Control Unit)		✓ 0
ZBE(Head Unit Display)		✓ 0
LIN:OBF(Upper Control Panel)		✓ 0
LIN:UBF-S(Head Unit Audio Operation Switch)		✓ 0
LIN:UBFL(Head Unit Controller Left Button)		✓ 0
LIN:UBFR(Head Unit Controller Right Button)		✓ 0
TPAD(TPAD)		✓ 0
LIN:UBFL_2(Head Unit Controller Left Button)		✓ 0
LIN:UBFR_2(Head Unit Controller Right Button)		✓ 0
ZAN(Center Display Control Unit)		✓ 0
MRM(Steering Column Control Unit)		✓ 0
FSCU(Fuel Pump Control Unit)		✗ 2
DTA(Telematics Service Control Unit)		✓ 0
DBE(Sunroof Control Unit)		✓ 0
LIN:AISP_2(Interior mirror)	ADAS	✓ 0

DTC (23)

ECM(Engine Control Unit) (3 DTCs)

DTC	Description	Status
P008A84	The pressure in the fuel low pressure circuit is too low. There is a signal below the permissible limit value.	Stored
P008A04	The pressure in the fuel low pressure circuit is too low. There is an internal fault.	Stored
P008700	The fuel pressure in the system is too low.	Stored

TCM(Transmission Control Unit) (6 DTCs)

DTC	Description	Status
U016800	Communication with the electronic ignition lock has a malfunction.	Stored(Event codes)

U012600	Communication with the steering column module has a malfunction.	Stored(Event codes)
U016831	Communication with the electronic ignition lock has a malfunction. The signal is not present.	Stored(Event codes)
U012802	Communication with the electric parking brake has a malfunction. There is a general signal fault.	Stored(Event codes)
P061B00	The torque calculation of the control unit has a malfunction.	Stored
P07B700	Sensor A of the park pawl has a sporadic malfunction.	Active and stored

ESP(Electronically controlled vehicle stability braking system control unit) (3 DTCs)

DTC	Description	Status
B23D1E3	The brake calipers have a malfunction.	Stored(Event codes)
B23D1E2	The brake calipers have a malfunction.	Stored(Event codes)
U11C300	There is a communication fault due to a short-term undervoltage.	Stored(Event codes)

SAMF(Front SAM signal acquisition control unit) (3 DTCs)

DTC	Description	Status
B181E64	The sensor for the engine hood has a malfunction. There is an implausible signal.	Stored
B1F4500	The starter battery has excessive resistance.	Stored
B23267B	Fill level sensor 'Washer fluid level' has a malfunction. The fluid level is too low.	Active and stored(Event codes)

EZS(Electronic Ignition Lock Control Unit) (1 DTC)

DTC	Description	Status
U116000	A bus keepawake unit was detected.	Stored(Event codes)

ES(Electric Power Steering) (1 DTC)

DTC	Description	Status
B210F00	Input 'Circuit 30' has a malfunction.	Stored(Event codes)

KLA(Air Conditioner Control Unit) (1 DTC)

DTC	Description	Status
B10A207	Left blend air flap servomotor fault - mechanical fault	Stored

HU(Head Unit Control Unit) (1 DTC)

DTC	Description	Status
B15A100	Login to the server has failed.	Stored(Event codes)

SW-SW-L(Left Headlamp Control Unit) (1 DTC)

DTC	Description	Status
-----	-------------	--------

U014100	Communication with the front signal acquisition and actuation module has a malfunction.	Stored(Event codes)
---------	---	---------------------

DMFR(Right Front Door Control Unit) (1 DTC)

DTC	Description	Status
B18B62A	Right front power window' switch fault - no signal change	Active and stored

FSCU(Fuel Pump Control Unit) (2 DTCs)

DTC	Description	Status
P008A00	The pressure in the fuel low pressure circuit is too low.	Stored
P008700	The fuel pressure in the system is too low.	Stored

Technician Notes
2017287138

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.