



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20241107112841  
Test Time: 2024-11-07 11:28:41  
Technician: Travino

# Volkswagen VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Volkswagen/AU/BE/BX - Golf 2013 USA/CAN >--  
VIN: WVVZZZAUZHWO30743

Odometer Reading: 116402km  
License Plate: N o n e r e g

## Customer Information

Name: Dekra MFC AUCTION HOUSE



















Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V21.00

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 16 )

System	Status/DTC
01 - Engine Control Module 1	 4
02 - Transmission electronics	 2
03 - Brakes 1	 3
08 - Air Conditioning	 3
09 - Electronic central electric	 5
15 - Airbag	 0
16 - Steering column electronics	 2
17 - Instrument cluster	 1
19 - Gateway	 1
20 - High beam assistant	 0
42 - Driver's door electronics	 4
44 - Power Steering	 2
52 - Passenger's door electronics	 4
55 - Headlight Regulation	  0
5F - Information electronics 1	 1
76 - Parking assistance	  1

## DTC ( 33 )

01 - Engine Control Module 1 ( 4 DTCs )



DTC	Description	Status
U112300	Databus error value received	Active/static
P164E00	Oil pressure regulation valve ,Electrical error	Passive/Sporadic
U042800	Steering angle sensor ,Range/performance	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Active/static

**02 - Transmission electronics ( 2 DTCs )**

DTC	Description	Status
P084100	Transmission fluid pressure sensor/switch A range/performance	Passive/Sporadic
U140000	Function restriction ,Caused by low voltage	Passive/Sporadic

**03 - Brakes 1 ( 3 DTCs )**

DTC	Description	Status
U140000	Function restriction ,Caused by low voltage	Passive/Sporadic
B1168F2	Steering angle sensor ,no initialization	Active/static
C114602	TPMS ,Signal error	Passive/Sporadic

**08 - Air Conditioning ( 3 DTCs )**

DTC	Description	Status
B10F000	Function restriction caused by compressor shut-off by engine	Passive/Sporadic
B10CE00	Blower reduction by energy management	Active/static
B10CD00	Function restriction caused by energy management	Passive/Sporadic

**09 - Electronic central electric ( 5 DTCs )**

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B12DD15	Rear lid Central Locking System Motor ,Open circuit/short circuit to B+	Passive/Sporadic
B147918	Remote control key 1 ,Voltage too low	Active/static
B147A18	Remote control key 2 ,Voltage too low	Passive/Sporadic
B1330F5	Anti-theft alarm system sensor ,Alert - emergency activation stage 1	Passive/Sporadic

**16 - Steering column electronics ( 2 DTCs )**

DTC	Description	Status
U140000	Function restriction ,Caused by low voltage	Passive/Sporadic

B116229	Gear selector lever park position lock switch ,Range/performance	Passive/Sporadic
---------	--	------------------

**17 - Instrument cluster ( 1 DTC )**

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

**19 - Gateway ( 1 DTC )**

DTC	Description	Status
U141100	Battery terminal recognition ,Open circuit	Active/static

**42 - Driver's door electronics ( 4 DTCs )**

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B148754	Motor for window regulator ,No basic setting	Passive/Sporadic
B131FF5	Driver side rear window regulator ,Voltage supply below lower limit	Passive/Sporadic
B132102	Driver side rear window regulator motor ,Signal fault	Passive/Sporadic

**44 - Power Steering ( 2 DTCs )**

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B1168F2	Steering angle sensor ,no initialization	Passive/Sporadic

**52 - Passenger's door electronics ( 4 DTCs )**

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B132C29	Window regulator button ,Range/performance	Passive/Sporadic
B148754	Motor for window regulator ,No basic setting	Passive/Sporadic
B1320F5	Passenger side rear window regulator ,Voltage supply below lower limit	Passive/Sporadic

**5F - Information electronics 1 ( 1 DTC )**

DTC	Description	Status
U140000	Function restriction ,Caused by low voltage	Passive/Sporadic

**76 - Parking assistance ( 1 DTC )**

DTC	Description	Status
U112300	Databus error value received	Passive/Sporadic

## Technician Notes

2016602524

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*