



CONDITION REPORT



Report No:  
2017292773  
DATE  
01/09/2026

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 01/09/2026        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 01/09/2026        |                     | Kempton Park - GT        |

Vehicle Data

|                 |                   |                         |              |
|-----------------|-------------------|-------------------------|--------------|
| Vehicle Type    | PASSENGER VEHICLE | Registered Owner        |              |
| Manufacturer    | JETOUR            | Registration Number     | MB72SGGP     |
| Model           | X70               | Register Number         |              |
| VIN             | HJRPBGFB5SF011257 | Date Of First Licensing |              |
| Engine Number   |                   | Last COR                |              |
| Doors           | 5                 | License Expiry Date     | 30/11/2026   |
| Color           | GREY              | Power / Displacement    |              |
| Year Model      |                   | Paint Finish            | M - METALLIC |
| Km Reading      | 37,990 KM         | Fuel                    | PETROL       |
| Cab / Body Type | STATION WAGON     | Transmission            | AUTOMATIC    |

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za


VIN: HJRPBGFB5SF011257



CONDITION REPORT



Report No:  
2017292773  
DATE  
01/09/2026



| Damage                                                | Repair Way |
|-------------------------------------------------------|------------|
| Switch Electrical Window Winder front right Defective | Repair     |
| Carpet Front Torn / Cut                               | Repair     |
| Door Front Left Paintwork • Scratched                 | Repair     |
| Door Rear Left Paintwork • Scratched                  | Repair     |
| Brake disc 2. Axle left Corrosion                     | Replace    |
| Brake disc 2. Axle right Corrosion                    | Replace    |

Brakes

Brake Test Results

|                     | Left               | Right              |                  |                                  |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
| Front               | 3.6                | 3.7                | -                |                                  |
| Rear                | 2.3                | 2.4                | -                |                                  |
| Emergency / Parking | 1                  | 1.2                | -                |                                  |

Tyres and Rims

Tyre Specification & Measurement

|             | Size       | Load/Speed Index | Manufacture | Model     | Type* | Production Date | Tread Depth (mm) |
|-------------|------------|------------------|-------------|-----------|-------|-----------------|------------------|
| Front Left  | 235/55R19  | 101V             | Wanli       | Flash     | V     | 3324            | 6 mm             |
| Front Right | 235/55R19  | 101V             | Wanli       | Flash     | V     | 3324            | 5 mm             |
| Rear Left   | 235/55R19  | 101V             | Wanli       | Flash     | V     | 3324            | 6 mm             |
| Rear Right  | 235/55R19  | 101V             | Wanli       | Flash     | V     | 3324            | 6 mm             |
| Spare       | T125/80D17 | 99M              | Westlake    | Temporary | V     | 0000            | 5 mm             |

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: HJRPBGFB5SF011257



## CONDITION REPORT



Report No:  
2017292773  
DATE  
01/09/2026

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System               | Code     | Description                               | Status |
|----|----------------------|----------|-------------------------------------------|--------|
| 1  | KEYLESS START SYSTEM | B1000-16 | BATTERY VOLTAGE - CIRCUIT VOLTAGE TOO LOW |        |

### Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Bottom of engine is fully covered.

Body • Exterior: Signs of spray work done on body panels.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: HJRPBGFB5SF011257



## CONDITION REPORT



Report No:

2017292773

DATE \_\_\_\_\_

01/09/2026

[illegible]

## Shock and brake report

[illegible]

Diagnostics report

| 英語の単語 | 和語          | 英語の単語       | 和語  |
|-------|-------------|-------------|-----|
| 1271  | translucent | translucent | 半透明 |
| 1272  | translucent | translucent | 半透明 |
| 1273  | translucent | translucent | 半透明 |
| 1274  | translucent | translucent | 半透明 |
| 1275  | translucent | translucent | 半透明 |
| 1276  | translucent | translucent | 半透明 |
| 1277  | translucent | translucent | 半透明 |
| 1278  | translucent | translucent | 半透明 |
| 1279  | translucent | translucent | 半透明 |
| 1280  | translucent | translucent | 半透明 |
| 1281  | translucent | translucent | 半透明 |
| 1282  | translucent | translucent | 半透明 |
| 1283  | translucent | translucent | 半透明 |
| 1284  | translucent | translucent | 半透明 |
| 1285  | translucent | translucent | 半透明 |
| 1286  | translucent | translucent | 半透明 |
| 1287  | translucent | translucent | 半透明 |
| 1288  | translucent | translucent | 半透明 |
| 1289  | translucent | translucent | 半透明 |
| 1290  | translucent | translucent | 半透明 |
| 1291  | translucent | translucent | 半透明 |
| 1292  | translucent | translucent | 半透明 |
| 1293  | translucent | translucent | 半透明 |
| 1294  | translucent | translucent | 半透明 |
| 1295  | translucent | translucent | 半透明 |
| 1296  | translucent | translucent | 半透明 |
| 1297  | translucent | translucent | 半透明 |
| 1298  | translucent | translucent | 半透明 |
| 1299  | translucent | translucent | 半透明 |
| 1300  | translucent | translucent | 半透明 |

Diagnostics report

[illegible]

Diagnostics report

[illegible]

Diagnostics report



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: HJRPBGFB5SF011257



## CONDITION REPORT



Report No:  
2017292773  
DATE  
01/09/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic transmission



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: HJRPBGFB5SF011257



## CONDITION REPORT



Report No:  
2017292773  
DATE  
01/09/2026



90 DEGREE RIGHT




90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: HJRPBGFB5SF011257



## CONDITION REPORT



Report No:  
2017292773  
DATE  
01/09/2026



RF TYRE TREAD



Sparewheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: HJRPBGFB5SF011257



## CONDITION REPORT



Report No:

2017292773

DATE

01/09/2026



CHASSIS



REAR



Oil cap and dipstick



Expansion bottle



Door Rear Left



Door Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: HJRPBGF55SF011257



## CONDITION REPORT



Report No:  
2017292773  
DATE  
01/09/2026



Brake disc 2. Axle left



Brake disc 2. Axle right



Carpet Front



Switch Electrical Window Winder front right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: HJRPBGF5SF011257