



CONDITION REPORT



Report No:
2017297260
DATE
10/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	10/09/2026		M57 Pretoria Road - 1619
Inspection Date	10/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	MAZDA	Registration Number	ML26GCGP
Model	CX-5 2.0L DYNAMIC AT [2022-2024]	Register Number	
VIN	JM6KF2W7AN0777519	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2026
Color	BLUE	Power / Displacement	
Year Model	2023	Paint Finish	TWO COAT UNI
Km Reading	104,853 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT



Report No:

2017297260

DATE

10/09/2026

Damage

Repair Way

Engine Wiring Defective	Repair
Windscreen Wiper Damaged	Replace
Seat Front Right Damaged	Repair
Seat Belt Front Right Damaged	Replace
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
A • Pillar Right Residual Traces of Repair	Repair
B • Pillar Right Damaged	Repair
C • Pillar Right Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Windscreen Chipped	Repair
Rim Front Right Scratched	Repair
Belly plates Damaged	Replace
Warning lights illuminated on dashboard	Repair
Airbag warning light intermittent	Repair
Signs of vehicle Airbags deployed	Replace
Rear left and right tyre sizes different	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.93	3.86	-	
Rear	2.44	2.57	-	
Emergency / Parking	2.05	2.24	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/65 R17	102H	Risten	Radial	V	4425	4 mm
Front Right	225/65 R17	102H	Risten	Radial	V	4425	4 mm
Rear Left	225/65 R17	102H	Hify	Vigorous	V	1617	1 mm
Rear Right	235/65 R17	108V	Goodyear	Efficient	V	0320	3 mm
Spare	T155/80 R17	100M	Bridgestone	Temporary	V	1222	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT



Report No:

2017297260

DATE

10/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PCM(POWERTRAIN CONTROL MODULE)	U0298:00-28	LOST COMMUNICATION WITH DC/DC CONVERTER CONTROL MO	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Rear right door plastic trim missing. Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels. Undercarriage: Bottom of engine and gearbox fully covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT



Report No:
2017297260
DATE
10/09/2026

Car				Car			
Brand	MAZDA	Model	MAZDA3	Brand	MAZDA	Model	MAZDA3
Year	2017	Registration	2017	Year	2017	Registration	2017
Color	Blue	Engine	1.8L	Color	Blue	Engine	1.8L
Transmission	Manual	Drive	Front	Transmission	Manual	Drive	Front
Test Date	2026/09/10	Test Time	10:30	Test Date	2026/09/10	Test Time	10:30
Test Result				Test Result			
Brake and shock absorber				Brake and shock absorber			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK
Brake				Brake			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK
Shock absorber				Shock absorber			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK

Brake and shock absorber report

Car				Car			
Brand	MAZDA	Model	MAZDA3	Brand	MAZDA	Model	MAZDA3
Year	2017	Registration	2017	Year	2017	Registration	2017
Color	Blue	Engine	1.8L	Color	Blue	Engine	1.8L
Transmission	Manual	Drive	Front	Transmission	Manual	Drive	Front
Test Date	2026/09/10	Test Time	10:30	Test Date	2026/09/10	Test Time	10:30
Test Result				Test Result			
Brake and shock absorber				Brake and shock absorber			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK
Brake				Brake			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK
Shock absorber				Shock absorber			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK

Diagnostic report page 1

Car				Car			
Brand	MAZDA	Model	MAZDA3	Brand	MAZDA	Model	MAZDA3
Year	2017	Registration	2017	Year	2017	Registration	2017
Color	Blue	Engine	1.8L	Color	Blue	Engine	1.8L
Transmission	Manual	Drive	Front	Transmission	Manual	Drive	Front
Test Date	2026/09/10	Test Time	10:30	Test Date	2026/09/10	Test Time	10:30
Test Result				Test Result			
Brake and shock absorber				Brake and shock absorber			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK
Brake				Brake			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK
Shock absorber				Shock absorber			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK

Diagnostic report page 2

Car				Car			
Brand	MAZDA	Model	MAZDA3	Brand	MAZDA	Model	MAZDA3
Year	2017	Registration	2017	Year	2017	Registration	2017
Color	Blue	Engine	1.8L	Color	Blue	Engine	1.8L
Transmission	Manual	Drive	Front	Transmission	Manual	Drive	Front
Test Date	2026/09/10	Test Time	10:30	Test Date	2026/09/10	Test Time	10:30
Test Result				Test Result			
Brake and shock absorber				Brake and shock absorber			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK
Brake				Brake			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK
Shock absorber				Shock absorber			
Front Left	OK	Front Right	OK	Front Left	OK	Front Right	OK
Rear Left	OK	Rear Right	OK	Rear Left	OK	Rear Right	OK

Diagnostic report page 3



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT



Report No:
2017297260
DATE
10/09/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT



Report No:
2017297260
DATE
10/09/2026



90 DEGREE REAR




90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT



Report No:

2017297260

DATE

10/09/2026



Spare Wheel and Accessories



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT



Report No:
2017297260
DATE
10/09/2026



Oil cap and dipstick



Seat Belt Front Right




B • Pillar Right



A • Pillar Right



Door Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT




Report No:
2017297260
DATE
10/09/2026



Door Rear Right



Rear Fender Right



C • Pillar Right



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT




Report No:
2017297260
DATE
10/09/2026



Rear Fender Left



Door Rear Left



Door Front Left



Windscreen Wiper



Side Mirror Left



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT



Report No:
2017297260
DATE
10/09/2026



Bonnet



Windscreen



Water level



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519



CONDITION REPORT



Report No:
2017297260
DATE
10/09/2026



Rim Front Right



Belly plates



Water level



Engine Wiring



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6KF2W7AN0777519