



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	10/09/2026		M57 Pretoria Road - 1619
Inspection Date	10/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	SUZUKI	Registration Number	KD05VCGP
Model	CELERIO 1.0 GA 5-DR [2017-2022]	Register Number	
VIN	MA3KFC42S00647107	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2027
Color	WHITE	Power / Displacement	
Year Model	2019	Paint Finish	TWO COAT UNI
Km Reading	99,941 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:

2017296824

DATE

10/09/2026

Damage

Repair Way

Center Console / Cubbyhole + Lid Missing	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Loose / Excessive Play	Repair
Interior Mirror Loose / Excessive Play	Repair
Hood Lining Defective	Repair
Door Panel Front Right Defective	Repair
Door Panel Rear Right Defective	Repair
Parcel Tray Missing	Replace
Dash Padding Damaged	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Front Bumper Damaged	Repair
Grill Cracked	Replace
Bonnet Damaged	Repair
A • Pillar Right Damaged	Repair
B • Pillar Left Damaged	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Repair
Door Rear Left Dented	Repair
Door Rear Right Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Rear Bumper / Mounting points Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Roof Damaged	Repair
Stabilizer Mounting Front Right Damaged	Replace
Chassis Dented	Repair
Sub Frame Scratched	Repair
Belly plates Damaged	Replace
Brakes Noisy	Repair
Signs of vehicle Airbags deployed	Replace
Aircon condenser dented	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.03	1.96	-	
Rear	1.15	0.88	-	
Emergency / Parking	1.03	0.87	-	

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	Goodyear	Efficient	V	4723	4 mm
Front Right	175/65R14	82H	Goodyear	Efficient	V	0224	5 mm
Rear Left	175/65R14	82H	Goodyear	Efficient	V	4422	3 mm
Rear Right	175/65R14	82H	Goodyear	Efficient	V	4422	3 mm
Spare	165/70R14	81S	Goodyear	Radial	V	2219	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS/ESP(ANTI-LOCK BRAKING SYSTEM/ELECTRONIC STABIL	C1057	POWER SUPPLY VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: Lights: Front left and right headlight lenses faded.
Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels. Signs of impact damage to the front and rear of the vehicle.
Axle and Suspension: Front and rear suspension noisy.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:

2017296824

DATE _____

10/09/2026

[illegible]

Brake and shock absorber report

[illegible]

Diagnostic report page 1

[illegible]

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



MANUAL



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:

2017296824

DATE

10/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Aircon condenser

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026



Oil cap and dipstick



Seat Front Right



Door Panel Front Right



Door Panel Rear Right



Seat Rear



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026



Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right



Bonnet



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026



Front Bumper



Front Bumper



Front Fender Left



Roof



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026



Rear Fender Left



A • Pillar Right



Rear bumper



Rear bumper



Rear bumper



Parcel Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026



Inner Boot Floor Pan and Spare Wheel Well



Hood Lining



Headlight Right



Headlight Left



Water level



Grill

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026



Sill Panel Left



Belly plates



Sub Frame



Sub Frame



Stabilizer Mounting Front Right



Chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107



CONDITION REPORT



Report No:
2017296824
DATE
10/09/2026



Chassis



Inner Boot Floor Pan and Spare Wheel Well



Rear Bumper / Mounting points



Water level



B • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3KFC42S00647107