



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 16/09/2026        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 16/09/2026        |                     | Kempton Park - GT        |

## Vehicle Data

|                 |                                   |                         |              |
|-----------------|-----------------------------------|-------------------------|--------------|
| Vehicle Type    | PASSENGER VEHICLE                 | Registered Owner        |              |
| Manufacturer    | FORD                              | Registration Number     | KTC025NW     |
| Model           | ECOSPORT 1.5 AMBIENTE [2016-2018] | Register Number         |              |
| VIN             | MAJAXXMRKAHB50284                 | Date Of First Licensing |              |
| Engine Number   |                                   | Last COR                |              |
| Doors           | 5                                 | License Expiry Date     |              |
| Color           | SILVER                            | Power / Displacement    |              |
| Year Model      | 2017                              | Paint Finish            | TWO COAT UNI |
| Km Reading      | 215,499 KM                        | Fuel                    | PETROL       |
| Cab / Body Type | HATCHBACK                         | Transmission            | MANUAL       |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za


VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026



| Damage                                                | Repair Way |
|-------------------------------------------------------|------------|
| Hoses Damaged                                         | Replace    |
| Water level Insufficient                              | Replace    |
| Air cleaner Damaged                                   | Replace    |
| Center Console / Cubbyhole + Lid Damaged              | Repair     |
| Windscreen Wiper Defective                            | Repair     |
| Air Conditioner Malfunction                           | Replace    |
| Headlight Left Damaged                                | Replace    |
| Headlight Right Scratched                             | Replace    |
| Seat Front Left Dirty                                 | Repair     |
| Seat Front Right Damaged                              | Repair     |
| Seat Rear Torn / Cut                                  | Repair     |
| Door Lock Front Right Damaged                         | Replace    |
| Carpet Front Damaged                                  | Repair     |
| Steering Wheel Trim Excessive Wear & Tear             | Repair     |
| Front Bumper Damaged                                  | Replace    |
| Grill Damaged                                         | Replace    |
| Bonnet Damaged                                        | Repair     |
| Bonnet slam plate (Shock tower/ Inner tray) Damaged   | Replace    |
| A • Pillar Left Paintwork • Scratched                 | Repair     |
| C • Pillar Left Residual Traces of Repair             | Repair     |
| C • Pillar Right Dented                               | Repair     |
| Front Fender Left Damaged                             | Repair     |
| Rear Fender Left Damaged                              | Repair     |
| Rear Fender Right Residual Traces of Repair           | Repair     |
| Door Front Left Paintwork • Chipmarks                 | Repair     |
| Door Front Right Dented                               | Repair     |
| Door Rear Left Paintwork • Scratched                  | Repair     |
| Door Rear Right Residual Traces of Repair             | Repair     |
| Boot Lid / Hatch door Residual Traces of Repair       | Repair     |
| Rear bumper Damaged                                   | Repair     |
| Sill Panel Left Paintwork • Scratched                 | Repair     |
| Sill Panel Right Damaged                              | Repair     |
| Windscreen Damaged                                    | Replace    |
| Stabilizer Mounting Front Left Defective              | Replace    |
| Stabilizer Mounting Front Right Defective             | Replace    |
| Control Arm Bush(es) Front Axle Right Cracked         | Replace    |
| Mounting Rubber(s) Rear Axle Left Cracked             | Replace    |
| Mounting Rubber(s) Rear Axle Right Cracked            | Replace    |
| Tyre Rear Left Damaged                                | Replace    |
| Tyre Rear Right Worn                                  | Replace    |
| Spare Tyre Torn / Cut                                 | Replace    |
| Rim Rear Left Scratched                               | Repair     |
| Rim Rear Right Scratched                              | Repair     |
| Sub Frame Scratched                                   | Repair     |
| Gearbox Mountings Cracked                             | Replace    |
| CV Joint(s) Boot(s) Front Left (inner/outer) Damaged  | Replace    |
| CV Joint(s) Boot(s) Front Right (inner/outer) Damaged | Replace    |
| Radiator Cradle Cracked                               | Repair     |
| Gear Selections Malfunction                           | Repair     |
| Front bumper stiffener damaged                        | Replace    |
| Rear left tyre regrooved                              | Replace    |
| Front left and right tyre sizes different             | Repair     |

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026

## Brakes

### Brake Test Results

|                     | Left               | Right              |                  |                                  |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
| Front               | 2.87               | 2.93               | -                |                                  |
| Rear                | 1.91               | 1.75               | -                |                                  |
| Emergency / Parking | 1.59               | 1.47               | -                |                                  |

## Tyres and Rims

### Tyre Specification & Measurement

|             | Size      | Load/Speed Index | Manufacture | Model     | Type* | Production Date | Tread Depth (mm) |
|-------------|-----------|------------------|-------------|-----------|-------|-----------------|------------------|
| Front Left  | 205/60R16 | 96V              | Velocity    | Rota-R    | V     | 2923            | 1 mm             |
| Front Right | 195/65R15 | 91V              | Symmetry    | SY201     | V     | 0421            | 1 mm             |
| Rear Left   | 205/60R16 | 92H              | Bridgestone | Turanza   | V     | 2211            | 0 mm             |
| Rear Right  | 205/60R16 | 92H              | Westlake    | Radial    | V     | 1322            | 0 mm             |
| Spare       | 205/60R16 | 92V              | Royalblack  | Royalmile | V     | 4923            | 1 mm             |

\* Tyre Legend: V=Virgin, R=Recap

## Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

## Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

## Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL. Interior: The vehicle interior is dirty, and the panels are scratched. Interior boot panel loose. Gear lever worn.

Body • Exterior: Poor residual traces of repair on body panels. Body panels are misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels. Signs of impact damage to the front of the vehicle.

Axle and Suspension: Front suspension faulty.

Undercarriage: Engine splash plate missing

## Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

## Technician

Sibusiso Mokase

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026

This document was created electronically and is valid without signature.

## General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT




Report No:  
2017299367  
DATE  
16/09/2026

| Vehicle Information  |            |                     |            | Inspection Results  |            |
|----------------------|------------|---------------------|------------|---------------------|------------|
| Vehicle No:          | 1234567    | Inspection No:      | 1234567    | Inspection Date:    | 16/09/2026 |
| Make:                | MAZDA      | Model:              | MAZDA3     | Year:               | 2017       |
| Engine:              | 2.0L       | Power:              | 115 kW     | Transmission:       | Manual     |
| Chassis No:          | 1234567890 | Inspection Date:    | 16/09/2026 | Inspection Time:    | 10:00 AM   |
| Inspector:           | J. Smith   | Vehicle Status:     | Pass       | Inspection Status:  | Complete   |
| Vehicle Weight:      | 1200 kg    | Engine Oil Level:   | OK         | Brake Fluid Level:  | OK         |
| Engine Oil Pressure: | OK         | Brake Pedal:        | OK         | Steering:           | OK         |
| Brake Pedal:         | OK         | Steering:           | OK         | Wheels:             | OK         |
| Steering:            | OK         | Wheels:             | OK         | Tires:              | OK         |
| Wheels:              | OK         | Tires:              | OK         | Chassis:            | OK         |
| Tires:               | OK         | Chassis:            | OK         | Engine Compartment: | OK         |
| Chassis:             | OK         | Engine Compartment: | OK         | Undercarriage:      | OK         |
| Engine Compartment:  | OK         | Undercarriage:      | OK         | Exhaust System:     | OK         |
| Undercarriage:       | OK         | Exhaust System:     | OK         | Lighting:           | OK         |
| Exhaust System:      | OK         | Lighting:           | OK         | Bodywork:           | OK         |
| Lighting:            | OK         | Bodywork:           | OK         | Interior:           | OK         |
| Bodywork:            | OK         | Interior:           | OK         | Exterior:           | OK         |
| Interior:            | OK         | Exterior:           | OK         | Overall Condition:  | Good       |
| Exterior:            | OK         | Overall Condition:  | Good       | Inspection Notes:   |            |

Brake and shock absorber report



Front chassis




Rear chassis

| Diagnostic Report   |            |
|---------------------|------------|
| Vehicle No:         | 1234567    |
| Inspection No:      | 1234567    |
| Inspection Date:    | 16/09/2026 |
| Inspection Time:    | 10:00 AM   |
| Inspector:          | J. Smith   |
| Vehicle Status:     | Pass       |
| Inspection Status:  | Complete   |
| Engine Oil Level:   | OK         |
| Brake Fluid Level:  | OK         |
| Steering:           | OK         |
| Wheels:             | OK         |
| Tires:              | OK         |
| Chassis:            | OK         |
| Engine Compartment: | OK         |
| Undercarriage:      | OK         |
| Exhaust System:     | OK         |
| Lighting:           | OK         |
| Bodywork:           | OK         |
| Interior:           | OK         |
| Exterior:           | OK         |
| Overall Condition:  | Good       |
| Inspection Notes:   |            |

Diagnostic report



Front bumper stiffener



Spare Wheel

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026



Oil cap and dipstick



Manual Transmission



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:

2017299367

DATE

16/09/2026



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284




## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ADDITIONAL 8

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026



ENGINE 1



Center Console / Cubbyhole + Lid



Steering Wheel Trim



Seat Front Right



C • Pillar Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026



Door Rear Right



Sill Panel Right



Door Front Right



Boot Lid / Hatch door



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026



Rear bumper



Spare Tyre



C • Pillar Left



Hoses



Headlight Right



Headlight Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026




Water level




Bonnet slam plate (Shock tower/ Inner tray)



Air cleaner



Front Fender Left



Door Front Left



Door Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026




Door Rear Left



Door Rear Left



Rear Fender Left



Seat Front Left



Seat Rear



Seat Rear

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026



Sill Panel Left



Front Bumper



Front Bumper



Front Bumper



Bonnet



Grill

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026



Grill



A • Pillar Left



Windscreen Wiper



Windscreen



Carpet Front



Control Arm Bush(es) Front Axle Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026




Rim Rear Left



Rim Rear Right



Gearbox Mountings



Sub Frame



Sub Frame



Stabilizer Mounting Front Left

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026



Stabilizer Mounting Front Right



Air cleaner



Radiator Cradle



CV Joint(s) Boot(s) Front Right (inner/outer)



CV Joint(s) Boot(s) Front Left (inner/outer)



Sill Panel Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284



## CONDITION REPORT



Report No:  
2017299367  
DATE  
16/09/2026



Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left



Tyre Rear Right



Tyre Rear Left



Air Conditioner



Door Lock Front Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: MAJAXXMRKAHB50284