



CONDITION REPORT



Report No:
2017297766
DATE
11/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	11/09/2026		M57 Pretoria Road - 1619
Inspection Date	11/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	CF125-560
Model	I10 1.1 MOTION 5-DR [2011-2018]	Register Number	
VIN	MALAN51BLHM694528	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	GREY	Power / Displacement	
Year Model	2017	Paint Finish	M - METALLIC
Km Reading	121,957 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM694528



CONDITION REPORT



Report No:

2017297766

DATE

11/09/2026

Damage

Repair Way

Parcel Tray Missing	Replace
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Front Fender Left Paintwork • Discoloured	Repair
Front Fender Right Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Parking Brake Performance Left / Right Difference out of legal range	Repair
Both front fender liner damage	Replace
Signs of water leak can not pin point water leak	Repair
Rear left tyre size differ	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.6	2.5	-	
Rear	0.7	0.6	-	
Emergency / Parking	1.1	0.6	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/60R14	75H	Annaite	An600	V	2925	3 mm
Front Right	165/60R14	75H	Annaite	An600	V	2625	3 mm
Rear Left	185/60R14	82H	Annaite	An600	V	3025	3 mm
Rear Right	165/60R14	75H	Annaite	An600	V	2925	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM694528



CONDITION REPORT



Report No:

2017297766

DATE

11/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	B1102	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM694528



CONDITION REPORT



Report No:

2017297766

DATE

11/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM694528



CONDITION REPORT



Report No:

2017297766

DATE

11/09/2026



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM694528



CONDITION REPORT



Report No:
2017297766
DATE
11/09/2026



RR TYRE TREAD



RF TYRE TREAD



No spare wheel



Coolant bottle



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM694528



CONDITION REPORT



Report No:
2017297766
DATE
11/09/2026



ENGINE 2




CHASSIS



VIN PLATE OR STICKER



LICENSE DISC



SHOCK AND BRAKE REPORT



DIAGNOSTIC REPORT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM694528



CONDITION REPORT



Report No:

2017297766

DATE

11/09/2026



Windscreen



Water level



Parcel Tray

Test date (day)	2026/09/11	Test date (month)	12/26	Test date (year)	2026	Test date (time)	12:26	Test date (location)	Malanville, Pretoria	Test date (operator)	Malanville, Pretoria
Test results											
Sub-type test											
Front axle	+ 3 - 4/10			Rear axle	- 3 - 4/10			Left axle	- 3 - 4/10		
Shock absorber test											
(RWD/4WD)											
Front axle	left	right	Difference	Weight	left	right	Difference	Weight	left	right	Difference
Rear axle	0.10	0.14	20 %	475 kg	0.10	0.14	20 %	475 kg	0.10	0.14	20 %
Total weight	0.10	0.14	40 %	1100 kg	0.10	0.14	40 %	1100 kg	0.10	0.14	40 %
Brake test											
Dry brake											
Front axle	left	right	Difference	Weight	left	right	Difference	Weight	left	right	Difference
Parking brake	0.10	0.14	20 %	475 kg	0.10	0.14	20 %	475 kg	0.10	0.14	20 %
Rear axle	0.10	0.14	20 %	475 kg	0.10	0.14	20 %	475 kg	0.10	0.14	20 %
Final evaluation water	0.10	0.14	20 %	475 kg	0.10	0.14	20 %	475 kg	0.10	0.14	20 %
Characteristics service brake	0.10	0.14	20 %	475 kg	0.10	0.14	20 %	475 kg	0.10	0.14	20 %
Deceleration parking brake	0.10	0.14	20 %	475 kg	0.10	0.14	20 %	475 kg	0.10	0.14	20 %
Total weight											
1100 kg											

Parking Brake Performance



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM694528



CONDITION REPORT



Report No:
2017297766
DATE
11/09/2026



Side Mirror Right



Front Fender Right



Front Bumper



Front Fender Left



Side Mirror Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM694528



CONDITION REPORT



Report No:
2017297766
DATE
11/09/2026



Door Rear Left



Rear Fender Left



Boot Lid / Hatch door



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM694528