



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	16/09/2026		M57 Pretoria Road - 1619
Inspection Date	16/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	LS68RZGP
Model	GRAND I10	Register Number	
VIN	MALB251ALRM529485	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	RED	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	58,515 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Damage	Repair Way
Radiator Defective	Repair
Air conditioner pipes Damaged	Replace
Air Conditioner Insufficient	Replace
Indicator Light Front Right Missing	Replace
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Seat Belt Rear Right Damaged	Replace
Hood Lining Damaged	Repair
Door Handle Rear Left Damaged	Replace
Door Sealing Rubber Front Right Damaged	Replace
Parcel Tray Damaged	Replace
Carpet Front Damaged	Repair
Boot Carpet Damaged	Replace
Mirror Adjusters Damaged	Replace
Front Bumper Damaged	Replace
Grill Damaged	Replace
Bonnet Damaged	Repair
A • Pillar Left Residual Traces of Repair	Repair
A • Pillar Right Residual Traces of Repair	Repair
B • Pillar Left Residual Traces of Repair	Repair
B • Pillar Right Residual Traces of Repair	Repair
C • Pillar Left Residual Traces of Repair	Repair
C • Pillar Right Damaged	Repair
Front Fender Right Residual Traces of Repair	Replace
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Front Fender Left / Inner Tray Damaged	Replace
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Residual Traces of Repair	Repair
Door Front Right Damaged	Replace
Door Rear Left Residual Traces of Repair	Replace
Door Rear Right Residual Traces of Repair	Replace
Boot Lid / Hatch door Damaged	Replace
Rear bumper Residual Traces of Repair	Repair
Inner Boot Floor Pan and Spare Wheel Well Paintwork • Scratched	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Roof Residual Traces of Repair	Repair
Windscreen Damaged	Replace
Window Front Door Right Damaged	Replace
Back Window Damaged	Replace
Tyre Front Left Damaged	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Spare Tyre Damaged	Replace
Rim Spare Wheel Damaged	Repair
Bolt(s) / Nut(s) Front Wheel Left Missing	Replace
Bolt(s) / Nut(s) Front Wheel Right Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026

Damage	Repair Way
Chassis Damaged	Repair
Radiator Cradle Damaged	Replace
Brakes Noisy	Repair
Vehicle license disk missing	Replace
Deceleration parking brake defective	Repair
Aircon condenser damaged	Replace
Front bumper stiffener damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	1.68	1.75	-	
Rear	1.68	1.75	-	
Emergency / Parking	1.04	0.66	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70 R14	81T	Goodyear	Assurance	V	0124	0 mm
Front Right	165/70 R14	81T	Goodyear	Assurance	V	0124	0 mm
Rear Left	165/70 R14	81T	Goodyear	Assurance	V	0124	1 mm
Rear Right	165/70 R14	81T	Goodyear	Assurance	V	0124	2 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AB(AIRBAG)	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Radiator and Aircon misaligned.

Interior: Vehicle interior dirty and panels scratched.

Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Signs of impact damage to front of vehicle.Bonnet slam plate plastic cover missing.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:

2017299411

DATE

16/09/2026

Tyres and Rims: Spare Wheel details not visible.
Undercarriage: Vehicle undercarriage dirty

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:

2017299411

DATE

16/09/2026

MAHA			
Vehicle No:	2017299411	Vehicle No:	2017299411
Owner:	MAHA	Owner:	MAHA
Model:	MAHA	Model:	MAHA
Year:	2017	Year:	2017
Engine:	1.5L	Engine:	1.5L
Transmission:	Manual	Transmission:	Manual
Drive:	Front	Drive:	Front
Color:	Red	Color:	Red
Inspection Date:	16/09/2026	Inspection Date:	16/09/2026
Inspection Time:	11:41 AM	Inspection Time:	11:41 AM
Inspection Location:	MAHA	Inspection Location:	MAHA
Inspection Status:	Pass	Inspection Status:	Pass
Inspection Notes:	All systems checked and found to be in good working order. No major issues identified.		

Brake and shock absorber report

AUTOS			
Vehicle No:	2017299411	Vehicle No:	2017299411
Owner:	MAHA	Owner:	MAHA
Model:	MAHA	Model:	MAHA
Year:	2017	Year:	2017
Engine:	1.5L	Engine:	1.5L
Transmission:	Manual	Transmission:	Manual
Drive:	Front	Drive:	Front
Color:	Red	Color:	Red
Inspection Date:	16/09/2026	Inspection Date:	16/09/2026
Inspection Time:	11:41 AM	Inspection Time:	11:41 AM
Inspection Location:	MAHA	Inspection Location:	MAHA
Inspection Status:	Pass	Inspection Status:	Pass
Inspection Notes:	All systems checked and found to be in good working order. No major issues identified.		

Diagnostic report page 1

AUTOS			
Vehicle No:	2017299411	Vehicle No:	2017299411
Owner:	MAHA	Owner:	MAHA
Model:	MAHA	Model:	MAHA
Year:	2017	Year:	2017
Engine:	1.5L	Engine:	1.5L
Transmission:	Manual	Transmission:	Manual
Drive:	Front	Drive:	Front
Color:	Red	Color:	Red
Inspection Date:	16/09/2026	Inspection Date:	16/09/2026
Inspection Time:	11:41 AM	Inspection Time:	11:41 AM
Inspection Location:	MAHA	Inspection Location:	MAHA
Inspection Status:	Pass	Inspection Status:	Pass
Inspection Notes:	All systems checked and found to be in good working order. No major issues identified.		

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:

2017299411

DATE

16/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:

2017299411

DATE

16/09/2026



No license disc



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Aircon condenser

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Front bumper stiffener



Oil cap and dipstick



Bonnet



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Grill



Headlight Right



Headlight Left



Roof



A • Pillar Right



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



B • Pillar Left



C • Pillar Left



Rear Fender Left



Door Rear Left



Hood Lining



Carpet Front

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Seat Front Right



Seat Front Right



Door Sealing Rubber Front Right



Seat Rear



Seat Rear



Seat Belt Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:

2017299411

DATE

16/09/2026



C • Pillar Right



B • Pillar Right




B • Pillar Right



Door Front Right



Door Rear Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:

2017299411

DATE

16/09/2026



Rear Fender Right



Boot Lid / Hatch door



Rear bumper



Rear bumper



Rear bumper



Tail Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Tail Light Left



Back Window



Parcel Tray



Boot Carpet



Spare Tyre



Rim Spare Wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Inner Boot Floor Pan and Spare Wheel Well



Door Front Left



Seat Front Left



Seat Front Left



Seat Rear



Door Handle Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Air Conditioner



Water level



Front Fender Right / Inner Tray



Bolt(s) / Nut(s) Front Wheel Right



Tyre Front Right



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Front Fender Left / Inner Tray



Sill Panel Left



Bolt(s) / Nut(s) Front Wheel Left



Bolt(s) / Nut(s) Rear Wheel Left



Tyre Rear Left



Bolt(s) / Nut(s) Rear Wheel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Sill Panel Right



Radiator Cradle



Radiator Cradle



Radiator Cradle



Tyre Front Right



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485



CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Air conditioner pipes



Chassis



Chassis



Chassis



Indicator Light Front Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485




CONDITION REPORT



Report No:
2017299411
DATE
16/09/2026



Radiator



Window Front Door Right



Mirror Adjusters



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALB251ALRM529485