



CONDITION REPORT



Report No:
2017294622
DATE
07/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	07/09/2026		M57 Pretoria Road - 1619
Inspection Date	07/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	MS63RFGP
Model	I20	Register Number	
VIN	MALBG513MTM384866	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	14,251 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG513MTM384866



CONDITION REPORT



Report No:

2017294622

DATE

07/09/2026

Damage

Repair Way

Door Handle Front Left Missing	Replace
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Dented	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
R/F fender liner damage	Replace
Body exterior	Impact damage at right front of vehicle
Body exterior	Signs of spray work done on some body panels

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.5	2.7	-	
Rear	2.0	2.1	-	
Emergency / Parking	1	1.5	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R17	88H	Bridgestone	Ecopia	V	2825	3 mm
Front Right	185/65R15	88H	Bridgestone	Ecopia	V	2825	3 mm
Rear Left	185/65R15	88H	Bridgestone	Ecopia	V	2825	3 mm
Rear Right	185/65R15	88H	Bridgestone	Ecopia	V	3025	3 mm
Spare	185/65R15	88H	Bridgestone	Ecopia	V	2825	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG513MTM384866



CONDITION REPORT



Report No:
2017294622
DATE
07/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG513MTM384866



CONDITION REPORT



Report No:

2017294622

DATE

07/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE FRONT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG513MTM384866



CONDITION REPORT



Report No:
2017294622
DATE
07/09/2026



ODOMETER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



Automatic



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MALBG513MTM384866



CONDITION REPORT



Report No:
2017294622
DATE
07/09/2026



RF TYRE TREAD



RR TYRE TREAD



Spare wheel



Coolant bottle



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG513MTM384866



CONDITION REPORT



Report No:

2017294622

DATE _____

07/09/2026



ENGINE 2



CHASSIS



VIN PLATE OR STICKER



LICENSE DISC

[illegible]

BRAKE TEST REPORT

[illegible]

DIAGNOSTIC REPORT PAGE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG513MTM384866



CONDITION REPORT




Report No:

2017294622

DATE

07/09/2026



DIAGNOSTIC REPORT PAGE 2

Test date:	2026/09/04	Vehicle:	HYUNDAI
Test driver:	15/06	Model:	HYUNDAI
Test results			
Side-slip test		Rear axle	
Shock absorber test (MSD3000)		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test		Rear axle	
Brake test			


Parking Brake Performance




Water level



Door Handle Front Left



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG513MTM384866



CONDITION REPORT



Report No:
2017294622
DATE
07/09/2026



Door Front Right



Front Fender Right



Side Mirror Right



Front Bumper



Front Bumper



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG513MTM384866



CONDITION REPORT



Report No:

2017294622

DATE

07/09/2026



Door Front Left



Side Mirror Left



Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG513MTM384866



CONDITION REPORT



Report No:
2017294622
DATE
07/09/2026



Rear bumper



Boot Lid / Hatch door



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBG513MTM384866