



CONDITION REPORT



Report No:
2017297487
DATE
11/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	11/09/2026		M57 Pretoria Road - 1619
Inspection Date	11/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	DW28RDGP
Model	I20 1.4 FLUID 5-DR [2015-2017]	Register Number	
VIN	MALBM51CLGM109108	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2027
Color	WHITE	Power / Displacement	
Year Model	2015	Paint Finish	C - COMMON
Km Reading	147,814 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MALBM51CLGM109108



CONDITION REPORT



Report No:
2017297487
DATE
11/09/2026



Damage	Repair Way
Switch Electrical Window Winder rear left Defective	Repair
Switch Electrical Window Winder rear right Defective	Repair
Seat Front Right Dirty	Repair
Seat Rear Dirty	Repair
Door Handle Front Right Damaged	Replace
Door Handle Rear Right Damaged	Replace
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Flaking	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Rear Fender Left Paintwork • Flaking	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Flaking	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Paintwork • Flaking	Repair
Rear bumper Paintwork • Scratched	Repair
Roof Paintwork • Flaking	Repair
Windscreen Cracked	Replace
Tyre Front Right Smooth	Replace
R/R quarter window broken	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.5	3.1	-	
Rear	2.0	2.2	-	
Emergency / Parking	1.6	1.6	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55R16	87V	Bridgestone	B250	V	1615	5 mm
Front Right	195/55R16	87H	Continental	Contact	V	2619	0 mm
Rear Left	195/55R16	87H	Continental	Contact	V	2719	5 mm
Rear Right	195/55R16	87H	Continental	Contact	V	2619	5 mm
Spare	195/55R16	87H	Goodyear	Ultragrip	V	0000	5 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CLGM109108



CONDITION REPORT



Report No:
2017297487
DATE
11/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AIRBAG	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Signs of spray work done on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MALBM51CLGM109108




CONDITION REPORT



Report No:
2017297487
DATE
11/09/2026



Shock and brake



Diagnostics report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CLGM109108



CONDITION REPORT



Report No:
2017297487
DATE
11/09/2026



ODOMETER



Manual transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CLGM109108



CONDITION REPORT




Report No:


2017297487

DATE


11/09/2026




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CLGM109108



CONDITION REPORT



Report No:

2017297487

DATE

11/09/2026



VIN PLATE OR STICKER




ENGINE 1



ENGINE 2



CHASSIS



REAR



Coolant reservoir

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CLGM109108



CONDITION REPORT



Report No:
2017297487
DATE
11/09/2026



Oil cap and dipstick



R/R window broken



Switch Electrical Window Winder rear left



Switch Electrical Window Winder rear right



Door Handle Rear Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CLGM109108



CONDITION REPORT



Report No:
2017297487
DATE
11/09/2026



Windscreen



Side Mirror Right



Door Front Right



Door Rear Right



Seat Rear



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CLGM109108



CONDITION REPORT



Report No:
2017297487
DATE
11/09/2026



Boot Lid / Hatch door



Rear Fender Left



Door Rear Left



Front Fender Left



Bonnet



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CLGM109108



CONDITION REPORT



Report No:

2017297487

DATE

11/09/2026



Front Bumper



Front Bumper



Front Bumper



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CLGM109108



CONDITION REPORT



Report No:
2017297487
DATE
11/09/2026



Tyre Front Right



Door Handle Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALBM51CLGM109108