



CONDITION REPORT



Report No:
2017295103
DATE
07/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	07/09/2026		M57 Pretoria Road - 1619
Inspection Date	07/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	SUZUKI	Registration Number	FVW994L
Model	DZIRE 1.2 GL MC [2020-2025]	Register Number	
VIN	MBHCZF63S00258751	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	
Color	RED	Power / Displacement	
Year Model	2022	Paint Finish	C - COMMON
Km Reading	131,976 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751



CONDITION REPORT



Report No:

2017295103

DATE

07/09/2026

Damage

Repair Way

Headlight Right Damaged	Replace
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Scratched	Repair
A • Pillar Left Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	
Radiator Cradle Dented	Repair
Body exterior	Vehicle got some scratches, stone chips and dents
Body exterior	Impact damage at front of vehicle
Foreign substance on oil cap	Repair
Both front fender liner missing	Replace
Both front fog lights malfunction	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.2	2.5	-	
Rear	1.6	1.0	-	
Emergency / Parking	1.1	0.8	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	92T	Dunlop	Sp touring	V	2024	3 mm
Front Right	185/65R15	92T	Dunlop	Sp touring	V	2024	3 mm
Rear Left	185/65R15	92T	Dunlop	Sp touring	V	1525	3 mm
Rear Right	185/65R15	92T	Dunlop	Sp touring	V	1525	3 mm
Spare	135/70R15	99M	Jk tyre	Temporary	V	1422	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
 www.dekraauto.co.za

VIN: MBHCZF63S00258751



CONDITION REPORT



Report No:

2017295103

DATE

07/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	C1091	POWER SUPPLY VOLTAGE	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751



CONDITION REPORT



Report No:
2017295103
DATE
07/09/2026

Vehicle Data			
Name/Car:	Car	Car	
Model:	2010/2011	Model:	2010/2011
Year:	2010/2011	Year:	2010/2011
Test date:	11/27	Test date:	11/27
Test results			
Shock test			
Front axle:	4.0 m/s	Rear axle:	4.0 m/s
Shock absorber test (MMS)			
Front axle:	0.8 m/s	Rear axle:	0.8 m/s
Shock absorber:	0.8 m/s	Shock absorber:	0.8 m/s
Brake test			
Front axle:	2.2 m/s	Rear axle:	2.2 m/s
Brake pedal:	1.1 m/s	Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s	Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s	Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s	Brake pedal:	1.1 m/s

Shock and brake report

Vehicle Data	
Name/Car:	Car
Model:	2010/2011
Year:	2010/2011
Test date:	11/27
Test results	
Shock test	
Front axle:	4.0 m/s
Rear axle:	4.0 m/s
Shock absorber test (MMS)	
Front axle:	0.8 m/s
Rear axle:	0.8 m/s
Brake test	
Front axle:	2.2 m/s
Rear axle:	2.2 m/s
Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s


Diagnostic report

Vehicle Data	
Name/Car:	Car
Model:	2010/2011
Year:	2010/2011
Test date:	11/27
Test results	
Shock test	
Front axle:	4.0 m/s
Rear axle:	4.0 m/s
Shock absorber test (MMS)	
Front axle:	0.8 m/s
Rear axle:	0.8 m/s
Brake test	
Front axle:	2.2 m/s
Rear axle:	2.2 m/s
Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s
Brake pedal:	1.1 m/s


Diagnostic report



Spare wheel



Coolant bottle



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751



CONDITION REPORT



Report No:
2017295103
DATE
07/09/2026



Manual



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751



CONDITION REPORT



Report No:
2017295103
DATE
07/09/2026



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751




CONDITION REPORT



Report No:
2017295103
DATE
07/09/2026



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751



CONDITION REPORT



Report No:
2017295103
DATE
07/09/2026



CHASSIS



Windscreen



Water level



Headlight Right



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751



CONDITION REPORT



Report No:
2017295103
DATE
07/09/2026



Front Bumper




Bonnet



A • Pillar Left



Side Mirror Left



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751



CONDITION REPORT



Report No:
2017295103
DATE
07/09/2026



Door Rear Left



Rear Fender Left



Boot Lid / Hatch door



Rear bumper



Rear bumper



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751



CONDITION REPORT



Report No:
2017295103
DATE
07/09/2026



Door Rear Right



Door Front Right




Front Fender Right



Side Mirror Right

side-slip test					
Front axle	- 6	m/km	Rear axle	- 4	m/km
Shock absorber test (MSD3000)					
	left	right	Difference	Weight	
Front axle	> 0,30	0,25	17 %	633 kg	
Rear axle	> 0,30	0,29	3 %	438 kg	
Total weight				1071 kg	
Brake test					
	Brake force		Difference		
	left	right			
Front axle	2,24 kN	2,57 kN	13 %		
Parking brake	1,10 kN	0,81 kN	27 %		
Rear axle	1,64 kN	1,03 kN	37 %		
Final evaluation static:					
Deceleration service brake:		71 %			
Deceleration parking brake:		48 %			
			Total weight	1071 kg	

Service Brake Performance Rear Axle



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751




CONDITION REPORT



Report No:
2017295103
DATE
07/09/2026



Radiator Cradle



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MBHCZF63S00258751