



CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	10/09/2026		M57 Pretoria Road - 1619
Inspection Date	10/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	HC39ZLGP
Model	KWID	Register Number	
VIN	MEEBBA00100522192	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/11/2026
Color	RED	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	148,417 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MEEBBA00100522192



CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026



Damage	Repair Way
Engine Oil Leak	Replace
Air cleaner Damaged	Repair
Tail Light Right Damaged	Replace
Dim Light Right Defective	Replace
Seat Front Left Torn / Cut	Repair
Seat Rear Torn / Cut	Repair
Door Lock Front Right Damaged	Repair
Steering Wheel Trim Damaged	Repair
Front Bumper Damaged	Replace
Bonnet Paintwork • Flaking	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Dented	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Dented	Repair
Boot Lid / Hatch Door Shock Left Defective	Repair
Boot Lid / Hatch Door Shock Right Defective	Repair
Windscreen Cracked	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Rear Left Smooth	Replace
Tyre Rear Right Smooth	Replace
Spare Tyre Smooth	Replace
Main Beam Right Damaged	Repair
Gearbox Mountings Damaged	Replace
Gearbox Oil Leak	Replace
Warning lights illuminated	Repair
Front tyre size differs	Replace
Rear tyre size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	1.7	1.5	-	
Rear	0.6	0.7	-	
Emergency / Parking	0.8	0.7	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:

2017297321

DATE

10/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	155/80R13	79T	Ceat	Milaze	V	2917	3 mm
Front Right	165/70R14	81T	Apollo	Amazer	V	4719	4 mm
Rear Left	155/80R13	79T	Sava	Effecta	V	2919	0 mm
Rear Right	165/65R13	77T	Tracmak	Privilo	V	0000	0 mm
Spare	155/80R13	79T	Ceat	Milaze	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJECTION	DTC010664	INLET PRESSURE CONSISTENCY VALUE OUTSIDE TOLERANCE	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: Body • Exterior: Residual traces of poor repair on body panels. Signs of spray work done on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026

SHOCKS				Results	
Wheel	Shock	Spring	Strut	Result	Remarks
Front Left	OK	OK	OK	OK	
Front Right	OK	OK	OK	OK	
Rear Left	OK	OK	OK	OK	
Rear Right	OK	OK	OK	OK	

Shock and brake report

DIAGNOSTICS		Results
Engine	OK	
Transmission	OK	
Brakes	OK	
Steering	OK	
Suspension	OK	
Electrical	OK	
Exhaust	OK	
Wheels/Tyres	OK	
Body/Chassis	OK	
Interior	OK	
Exterior	OK	


Diagnostics report

DIAGNOSTICS		Results
Engine	OK	
Transmission	OK	
Brakes	OK	
Steering	OK	
Suspension	OK	
Electrical	OK	
Exhaust	OK	
Wheels/Tyres	OK	
Body/Chassis	OK	
Interior	OK	
Exterior	OK	

Diagnostics report

DIAGNOSTICS		Results
Engine	OK	
Transmission	OK	
Brakes	OK	
Steering	OK	
Suspension	OK	
Electrical	OK	
Exhaust	OK	
Wheels/Tyres	OK	
Body/Chassis	OK	
Interior	OK	
Exterior	OK	

Diagnostics report



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:

2017297321

DATE

10/09/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual transmission



90 DEGREE FRONT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:

2017297321

DATE

10/09/2026



90 DEGREE REAR



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:

2017297321

DATE

10/09/2026



Sparewheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026



REAR



Warning lights illuminated



Dipstick



Coolant reservoir



Oil cap



Dim Light Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026



Tail Light Right



Seat Rear



Seat Front Left



Steering Wheel Trim



Front Fender Right



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026




Windscreen



Door Front Right




Door Rear Right



Rear Fender Right



Rear Fender Right



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026



Boot Lid / Hatch door



Spare Tyre



Boot Lid / Hatch Door Shock Right



Boot Lid / Hatch Door Shock Left



Door Lock Front Right



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MEEBBA00100522192



CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026



Door Front Left



Bonnet



Air cleaner



Main Beam Right



Main Beam Right



Main Beam Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026




Bonnet



Control Arm Bush(es) Front Axle Right



Front Bumper



Front Bumper



Control Arm Bush(es) Front Axle Left



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192




CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026



Gearbox



Gearbox



Gearbox Mountings



Gearbox Mountings



Engine



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192



CONDITION REPORT



Report No:
2017297321
DATE
10/09/2026




Engine




Main Beam Right



Front Bumper



Tyre Rear Left



Tyre Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00100522192