



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	14/09/2026		M57 Pretoria Road - 1619
Inspection Date	14/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	KNG155MP
Model	KWID	Register Number	
VIN	MEEBBA00700798358	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2025
Color	GREEN	Power / Displacement	
Year Model		Paint Finish	PEARL EFFECT
Km Reading	40,492 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MEEBBA00700798358



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026



Damage	Repair Way
Engine Oil Leak	Repair
Under bonnet insulation cover Damaged	Repair
Seat Front Left Dirty	Repair
Seat Front Right Dirty	Repair
Seat Rear Dirty	Repair
Parcel Tray Missing	Replace
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
A • Pillar Left Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Paintwork • Scratched	Repair
Roof Dented	Repair
Windscreen Damaged	Replace
Brake Pad 1. Axle left Excessive Wear & Tear	Replace
Shock Absorber Front Right Sweat	Replace
Shock Absorber Rear Left Sweat	Replace
Shock Absorber Rear Right Sweat	Replace
Control Arm(s) Front Axle Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Spare Tyre Worn	Replace
Engine to silencer pipe Leak	Repair
Triangle Missing	Replace
Front right shock absorber weak	Replace
Foreign substance on oil cap	Repair
Engine cover damaged	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.15	1.85	-	
Rear	1.3	1.23	-	
Emergency / Parking	0.73	0.93	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70 R14	81T	Apollo	Amazer	V	4421	2 mm
Front Right	165/70 R14	81T	Apollo	Amazer	V	4621	0 mm
Rear Left	165/70 R14	81T	Apollo	Amazer	V	4521	0 mm
Rear Right	165/70 R14	81T	Apollo	Amazer	V	4621	0 mm
Spare	165/70 R14	81T	Apollo	Amazer	V	4521	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJ(INJECTION)	DTC033564	ENGINE SPEED SENSOR SIGNAL PLAUSIBILITY	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Interior: Bonnet release handle not opening. Vehicle interior dirty and panels scratched.
Body • Exterior: Dents and scratches on body panels
Tyres and Rims: Spare Wheel deflated.
Undercarriage: Vehicle undercarriage dirty. Signs of surface rust on undercarriage.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358

**CONDITION REPORT**

Report No:
2017298575
DATE
14/09/2026

strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:

2017298575

DATE _____

14/09/2026

[illegible]

Brake and shock absorber report

The image shows a close-up of a Renault vehicle's instrument cluster. At the top, the word "RENAULT" is displayed in red. Below it, the text "ROBSTER VEHICLE DASHBOARD" is visible. The dashboard features several analog gauges and digital displays. On the left, there is a speedometer with a needle pointing to 0. In the center, there is a digital display showing "000000". On the right, there is a digital display showing "000000". Below the speedometer, there is a digital display showing "000000". At the bottom, there is a digital display showing "000000". The dashboard is black with red and white markings.

Diagnostic report page 1

Review ID: 0000	Test Time: 2025-09-14 10:09:59	Report ID: SAAXIA20250914159959
Customer name: _____		
Technician: _____		
Date: _____		
Note: Please save a copy of this report for your records.		

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:

2017298575

DATE

14/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026



Engine cover



Seat Front Right



Seat Rear



Door Rear Right



Door Rear Right



Door Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358




CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026



Door Front Right



Front Fender Right



Bonnet



Front Fender Left



Front Fender Left



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026



Door Front Left



Door Front Left



Door Rear Left



Rear Fender Left



Rear Fender Left



Side Mirror Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026



Seat Front Left



Seat Rear



Boot Lid / Hatch door



Rear bumper



Rear bumper



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT




Report No:
2017298575
DATE
14/09/2026



Windscreen



Parcel Tray



Inner Boot Floor Pan and Spare Wheel Well



Spare Tyre



Under bonnet insulation cover



Shock Absorber Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026



Control Arm Bush(es) Front Axle Right



Front Bumper



Front Bumper



Control Arm Bush(es) Front Axle Left



Engine



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026



Brake Pad 1. Axle left



Control Arm(s) Front Axle Right



Mounting Rubber(s) Rear Axle Left



Tyre Rear Right



Tyre Rear Left



Shock Absorber Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358



CONDITION REPORT



Report No:
2017298575
DATE
14/09/2026



Shock Absorber Rear Right



Engine to silencer pipe



Side Mirror Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00700798358