



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	08/09/2026		M57 Pretoria Road - 1619
Inspection Date	08/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	KD84XHGP
Model	KWID	Register Number	
VIN	MEEBBA00900774448	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/10/2025
Color	RED	Power / Displacement	
Year Model		Paint Finish	TWO COAT UNI
Km Reading	110,771 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:

2017295665

DATE

08/09/2026

Damage

Repair Way

Engine Oil Leak	Repair
Engine Wiring Defective	Replace
Hoses Damaged	Replace
Expansion Bottle Damaged	Replace
Air conditioner pipes Damaged	Replace
Air cleaner Damaged	Replace
Indicator Light Front Left Damaged	Replace
Indicator Light Front Right Damaged	Replace
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Number Plate Light Left Missing	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Dirty	Repair
Seat Rear Dirty	Repair
Hood Lining Dirty	Repair
Door Sealing Rubber Front Left Damaged	Replace
Door Sealing Rubber Rear Left Damaged	Replace
Door Sealing Rubber Rear Right Damaged	Replace
Parcel Tray Damaged	Replace
Side Mirror Right Paintwork • Scratched	Repair
Grill Damaged	Replace
Bonnet Damaged	Replace
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
A • Pillar Left Residual Traces of Repair	Repair
A • Pillar Right Residual Traces of Repair	Repair
C • Pillar Left Residual Traces of Repair	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Residual Traces of Repair	Repair
Front Fender Left / Inner Tray Damaged	Repair
Front Fender Right / Inner Tray Damaged	Replace
Rear Fender Left / Inner Tray Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Dented	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Roof Dented	Repair
Windscreen Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Rear Left Damaged	Replace
Spare Tyre Damaged	Replace
Main Beam Left Damaged	Repair
Main Beam Right Damaged	Repair
Chassis Scratched	Repair
Sub Frame Dented	Repair



DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026

Damage	Repair Way
Gearbox Mountings Cracked	Replace
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
Radiator Cradle Damaged	Replace
Intake manifold damaged	Replace
Aircon condenser missing	Replace
Loose sound wiring inside of vehicle	Replace
Front bumper stiffener damaged	Replace
Fan Cowley damaged	Replace
Engine oil sump damaged	Replace
Rear left tyre regrooved	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.14	2.09	-	
Rear	1.0	1.2	-	
Emergency / Parking	1.01	1.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70 R14	81T	Apollo	Amazer	V	1421	1 mm
Front Right	165/70 R14	81T	Apollo	Amazer	V	1821	2 mm
Rear Left	165/70 R14	81T	Apollo	Amazer	V	0221	0 mm
Rear Right	165/70 R14	81T	Apollo	Amazer	V	1921	2 mm
Spare	165/70 R14	81T	Apollo	Amazer	V	1721	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJ(INJECTION)	DTC011517	WATER TEMPERATURE SENSOR CIRCUIT VOLTAGE TOO HIGH	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE EXTERIOR AND INTERIOR ELECTRICAL AND MECHANICAL PARTS. Interior: Vehicle interior dirty and panels scratched. Boot release handle not opening.
Body • Exterior: Poor residual traces of repair on body panels. Body panels misaligned. Stone chips and spray work on body panels. Dents and scratches on body panels. Signs of impact damage to front and rear of vehicle. Bonnet struggles to open.
Road Test: Gear selection faulty.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



LICENSE DISC



VIN PLATE OR STICKER



FRONT RIGHT CORNER



90 DEGREE FRONT



90 DEGREE LEFT



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



90 DEGREE REAR



90 DEGREE RIGHT



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



RR TYRE TREAD



ENGINE 1



RF TYRE TREAD



Oil cap and dipstick



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026




LF TYRE TREAD



LR TYRE TREAD



Spare Wheel and Accessories



Brake and shock absorber report



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA0900774448



CONDITION REPORT



Report No:

2017295665

DATE

08/09/2026



Diagnostic report page 3



Loose sound wiring



Intake manifold



Front bumper stiffener



Fan Cowley



Engine oil sump

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Hood Lining



Seat Front Right



Seat Rear



Door Sealing Rubber Rear Right



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448




CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Door Front Right



Front Fender Right



A • Pillar Right



Side Mirror Right



Windscreen



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Grill



Headlight Right



Headlight Left



Indicator Light Front Right



Indicator Light Front Left



Indicator Light Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Front Fender Left



A • Pillar Left



Door Front Left



Door Rear Left



Rear Fender Left



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Door Sealing Rubber Front Left



Door Sealing Rubber Rear Left



Tail Light Left



Tail Light Right



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026




Rear bumper



Boot Lid / Hatch door



Roof



Main Beam Right



Engine Wiring



Engine Wiring

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Air conditioner pipes




Air conditioner pipes



Air cleaner



Engine Wiring



Engine Wiring



Front Fender Left / Inner Tray

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026




Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Main Beam Right



Radiator Cradle



Parcel Tray



C • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Rear Fender Left / Inner Tray



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Spare Tyre

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Spare Tyre



Front Fender Right / Inner Tray



Control Arm Bush(es) Front Axle Right



Control Arm Bush(es) Front Axle Left



Main Beam Left



Main Beam Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Sill Panel Left



Rear Fender Left / Inner Tray



Main Beam Left



Number Plate Light Left



Sill Panel Right



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Main Beam Left



CV Joint(s) Boot(s) Front Left (inner/outer)



Sub Frame



Gearbox Mountings



Engine



Main Beam Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Sub Frame



Chassis



Chassis



Chassis



Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Tyre Rear Left



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Main Beam Right



Hoses



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448



CONDITION REPORT



Report No:
2017295665
DATE
08/09/2026



Expansion Bottle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MEEBBA00900774448