



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	09/09/2026		M57 Pretoria Road - 1619
Inspection Date	09/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	RENAULT	Registration Number	HD95NTGP
Model	CLIO	Register Number	
VIN	VF15RSV0A58010309	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	200,893 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026



Damage

Repair Way

Switch Electrical Window Winder front right Defective	Repair
Indicator Light Front Left Damaged	Replace
Tail Light Left Damaged	Replace
Headlight Left Damaged	Replace
Seat Front Left Torn / Cut	Repair
Seat Front Right Torn / Cut	Repair
Seat Rear Torn / Cut	Repair
Side Mirror Left Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Boot Lid / Hatch Door Shock Left Defective	Replace
Boot Lid / Hatch Door Shock Right Defective	Replace
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Rim Front Right Deformed	Repair
R/F electric window not working	Repair
Front suspension excessive knocking noise	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.63	3.15	-	
Rear	1.95	2.14	-	
Emergency / Parking	1.26	1.65	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Invovic	EL601	V	3825	5 mm
Front Right	185/65R15	88H	Invovic	EL601	V	3825	4 mm
Rear Left	185/65R15	88H	Invovic	EL601	V	3825	6 mm
Rear Right	185/65R15	88H	Invovic	EL601	V	3825	6 mm
Spare	185/65R15	88H	Royal black	Royal mile	V	0000	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	INJECTION	DTC001177	INLET CAMSHAFT SHIFTER ASSISTANCE FAULT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, EXTERIOR, AND MECHANICAL PARTS. RESIDUAL TRACES OF POOR REPAIR AND SIGNS OF SPRAY WORK DONE ON BODY PANELS. THE ENGINE AND UNDERCARRIAGE WERE FULLY COVERED.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:

2017296281

DATE

09/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



MANUAL GEAR LEVER



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026



LR TYRE TREAD



RR TYRE TREAD



ENGINE 1



ENGINE 2



CHASSIS



CHASSIS 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:

2017296281

DATE

09/09/2026



OIL CAP AND DIPSTICK



EXPANSION BOTTLE



WINDSCREEN WASHER BOTTLE



SPARE WHEEL



LEFT FRONT FENDER LINER LOOSE



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309




CONDITION REPORT




Report No:
2017296281
DATE
09/09/2026




VIN PLATE OR STICKER




SHOCK AND BRAKE TEST REPORT



DIAGNOSTIC TEST REPORT



DIAGNOSTIC TEST REPORT



DIAGNOSTIC TEST REPORT



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026



Seat Rear



Seat Rear



Seat Front Right



Switch Electrical Window Winder front right



Windscreen



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026



Front Fender Right



Door Front Right



Door Front Right



Door Rear Right



Rear Fender Right



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026



Boot Lid / Hatch Door Shock Right



Boot Lid / Hatch Door Shock Left



Tail Light Left



Rear Fender Left



Rear Fender Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026



Door Rear Left



Door Front Left



Front Fender Left



Side Mirror Left



Water level



Headlight Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026



Stabilizer Mounting Front Right



Front Bumper



Front Bumper



Front Bumper



Front Bumper



Stabilizer Mounting Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309



CONDITION REPORT



Report No:
2017296281
DATE
09/09/2026



Rear bumper



Rear bumper



Rear bumper



Rim Front Right



Indicator Light Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: VF15RSV0A58010309