



CONDITION REPORT



Report No:

2017299072

DATE

15/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	15/09/2026		M57 Pretoria Road - 1619
Inspection Date	15/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	AUDI	Registration Number	CK43BHGP
Model	A4 1.8T FSI S 125KW MULTITRONIC [2012-2014]	Register Number	
		Date Of First Licensing	
VIN	WAUZZZ8K8DA161801	Last COR	
Engine Number		License Expiry Date	31/08/2026
Doors	4	Power / Displacement	
Color	GREY	Paint Finish	M - METALLIC
Year Model	2013	Fuel	PETROL
Km Reading	209,516 KM	Transmission	AUTOMATIC
Cab / Body Type	SEDAN		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WAUZZZ8K8DA161801



CONDITION REPORT



Report No:
2017299072
DATE
15/09/2026



Damage	Repair Way
Engine Oil Leak	Repair
Tail Light Left Damaged	Replace
Seat Front Left Cracked	Repair
Seat Front Right Torn / Cut	Repair
Sun Visor Right Damaged	Repair
Side Mirror Left Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Residual Traces of Repair	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Damaged	Repair
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Gear Selections Slippy Hesitation	Repair
Signs of water leak can not pin point water leak	Repair
Gear box faulty	Repair
Front and rear tires deferred name brand	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	4.3	4.8	-	
Rear	2.1	2.4	-	
Emergency / Parking	2.3	2.3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	245/40R18	97Y	Bridgestone	Turanza	V	4325	3 mm
Front Right	245/40R18	97Y	Bridgestone	Turanza	V	4125	3 mm
Rear Left	245/40R18	93W	Dunlop	Sp sport	V	0923	3 mm
Rear Right	245/40R18	93W	Dunlop	Sp sport	V	0923	3 mm
Spare	T125/70R19	100M	Hankook	Temporary	V	2812	4 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801



CONDITION REPORT



Report No:
2017299072
DATE
15/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PASSIVE SPORADIC	U101100	SUPPLY VOLTAGE VOLTAGE TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Signs of spray work done on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801



CONDITION REPORT




Report No:


2017299072

DATE

15/09/2026




Shock and brake report



Diagnostic report




Diagnostic report



Diagnostic report



Diagnostic report



Diagnostic report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801



CONDITION REPORT



Report No:

2017299072

DATE

15/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801



CONDITION REPORT



Report No:
2017299072
DATE
15/09/2026



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801



CONDITION REPORT



Report No:
2017299072
DATE
15/09/2026



RR TYRE TREAD



RF TYRE TREAD



Spare wheel



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801



CONDITION REPORT



Report No:
2017299072
DATE
15/09/2026



ENGINE 2



CHASSIS



Expenditure bottle



Oil cap



Water level



Sun Visor Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801



CONDITION REPORT



Report No:
2017299072
DATE
15/09/2026



Bonnet



Tail Light Left



Boot Lid / Hatch door



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801



CONDITION REPORT



Report No:
2017299072
DATE
15/09/2026



Rear Fender Left



Door Rear Left



Door Front Left



Side Mirror Left



Front Fender Left



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801



CONDITION REPORT



Report No:
2017299072
DATE
15/09/2026



Front Bumper



Front Fender Right



Door Front Right



Door Rear Right



Rear Fender Right



CV Joint(s) Boot(s) Front Right (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801



CONDITION REPORT



Report No:
2017299072
DATE
15/09/2026



Engine



Seat Front Right



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WAUZZZ8K8DA161801