



CONDITION REPORT



Report No:
2017297947
DATE
11/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	11/09/2026		M57 Pretoria Road - 1619
Inspection Date	11/09/2026		Kempton Park -

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	MERCEDES-BENZ	Registration Number	CBS56453
Model	C320 CDI ELEGANCE 7-SP DSL AT [2007-2009]	Register Number	
VIN	WDD2040222R037501	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	30/04/2026
Color	SILVER	Power / Displacement	
Year Model	2009	Paint Finish	M - METALLIC
Km Reading	325,860 KM	Fuel	DIESEL
Cab / Body Type	SEDAN	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040222R037501



CONDITION REPORT



Report No:

2017297947

DATE

11/09/2026

Damage

Repair Way

Engine Oil Leak	Repair
Water level Insufficient	Repair
Alternator Damaged	Repair
Bonnet stay and shocks Defective	Repair
Switch Electrical Window Winder front left Defective	Repair
Gear Lever Dust Boot Torn / Cut	Repair
Front Bumper Paintwork • Scratched	Repair
Grill Damaged	Repair
Bonnet Dented	Repair
Door Front Left Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Replace
Service Brake Performance Rear Axle Left / Right	Repair
Difference out of legal range	Repair
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Radius Rod(s) Front Axle Right Damaged	Replace
Ball Joint(s) Front Axle Left Damaged	Replace
Tyre Front Left Torn / Cut	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Smooth	Replace
Rim Rear Left Cracked	Repair
Engine to silencer pipe Leak	Repair
Gearbox Oil Leak	Repair
Engine Performance Insufficient	Repair
Gear Selections Malfunction	Repair
Warning lights illuminated	Repair
Vehicle electronics malfunction.	Repair
No battery	Replace
Undercarriage	Is fully covered

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	4.2	3.4	-	
Rear	0.6	0.0	-	
Emergency / Parking	2.6	2.3	-	

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040222R037501



CONDITION REPORT



Report No:
2017297947
DATE
11/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	225/45R17	94W	Royal black	Mile	V	4628	4 mm
Front Right	225/45R17	94W	Royal black	Mile	V	3523	0 mm
Rear Left	225/45R17	94W	Goodride	SA	V	3024	0 mm
Rear Right	225/45R17	94W	Goodride	SA	V	1524	1 mm
Spare	225/45R17	94W	Durun	L919	V	0000	1 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

A vehicle diagnostic has not been conducted.

Diagnostic could not be performed due to no data available and or OBD interface malfunction.

Inspection Conditions

No Test Drive

Vehicle doesn't start

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Engine Compartment: Bottom of engine is fully covered.

Body • Exterior: Signs of spray work done on body panels.

Undercarriage: Undercarriage Is fully covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks:

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD204022R037501



CONDITION REPORT




Report No:

2017297947

DATE

11/09/2026



Shock and brake report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD204022R037501



CONDITION REPORT



Report No:
2017297947
DATE
11/09/2026



Automatic transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040222R037501



CONDITION REPORT



Report No:

2017297947

DATE

11/09/2026



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040222R037501



CONDITION REPORT



Report No:
2017297947
DATE
11/09/2026



ENGINE 1



ENGINE 2



CHASSIS



REAR



Warning lights illuminated



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040222R037501



CONDITION REPORT



Report No:
2017297947
DATE
11/09/2026



Expansion bottle



No battery



Warning lights illuminated



Gear Lever Dust Boot



Bonnet



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD204022R037501



CONDITION REPORT



Report No:
2017297947
DATE
11/09/2026



Alternator




Alternator



Alternator



Switch Electrical Window Winder front left



Service Brake Performance Rear Axle



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040222R037501



CONDITION REPORT



Report No:
2017297947
DATE
11/09/2026



Front Bumper



Tyre Front Left



Door Front Left



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040222R037501



CONDITION REPORT



Report No:
2017297947
DATE
11/09/2026



Stabilizer Mounting Front Left



Ball Joint(s) Front Axle Left



Radius Rod(s) Front Axle Right



Stabilizer Mounting Front Right



Engine



Engine to silencer pipe

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040222R037501



CONDITION REPORT



Report No:
2017297947
DATE
11/09/2026



Gearbox



Tyre Rear Left




Rim Rear Left



Bonnet stay and shocks



Grill



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WDD2040222R037501