



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	17/09/2026		M57 Pretoria Road - 1619
Inspection Date	17/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	VOLKSWAGEN	Registration Number	KV09XMGP
Model	TIGUAN 2.0 TDI SPORT&STYLE DSL 4MOTION DSG [2011-2015]	Register Number	
		Date Of First Licensing	
VIN	WVGZZZ5NZEW095117	Last COR	
Engine Number		License Expiry Date	31/08/2026
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2014	Fuel	DIESEL
Km Reading	185,137 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: WVGZZZ5NZEW095117



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026



Damage	Repair Way
Hood Lining Damaged	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Front Fender Right / Inner Tray Damaged	Replace
Door Front Left Dented	Replace
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Chipmarks	Repair
Boot Lid / Hatch door Paintwork • Chipmarks	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Cracked	Replace
Belly plates Damaged	Repair
Gearbox Oil Leak	Repair
Differential Oil Leak	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Defective	Replace
Brakes Shudder	Repair
Front emblem cracked	Replace

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	-	-	-	
Rear	-	-	-	
Emergency / Parking	-	-	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	235/55Z R17	103W	Rapid	P609	V	3525	5 mm
Front Right	235/55Z R17	103W	Rapid	P609	V	3525	5 mm
Rear Left	235/55Z R17	103W	Rapid	P609	V	0121	1 mm
Rear Right	235/55Z R17	103W	Rapid	P609	V	1521	1 mm
Spare	T145/80 R18	99M	Continental	Temporary	V	0714	3 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZEW095117



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	03-BRAKES 1	02214:002	TIRE PRESSURE WARNING-LOWER LIMIT NOT REACHED	

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Minor dents and scratches on body panel Residual traces of repair on body panels. Stone chips and spray work on body panels.

Axle and Suspension: Front suspension faulty

Undercarriage: Bottom of engine and gearbox fully covered.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZEW095117



CONDITION REPORT



Report No:

Report No.
2017300402

DATE _____

17/09/2026

[illegible]

Shock absorber report

[illegible]

Diagnostic report page 1

[illegible]

Diagnostic report page 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZEW095117



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVZZZ5NZEW095117



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare Wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZEW095117



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZEW095117



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026



Front emblem



Hood Lining



Door Front Right



Door Front Right



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZEW095117



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026



Boot Lid / Hatch door



Boot Lid / Hatch door



Door Rear Left



Door Rear Left



Door Front Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZEW095117



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026



Windscreen



Bonnet



Bonnet



Front Fender Right



Side Mirror Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZZ5NZEW095117



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026



Front Fender Right / Inner Tray



Front Bumper



Front Bumper



Stabilizer Mounting Front Left



Stabilizer Mounting Front Right



Control Arm Bush(es) Front Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVZZZ5NZEW095117



CONDITION REPORT



Report No:
2017300402
DATE
17/09/2026



CV Joint(s) Boot(s) Front Left (inner/outer)



Gearbox



Differential



Belly plates



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: WVGZZ5NZEW095117