



## CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026

MFC Auction House  
M57 Pretoria Rd, Glenmarais, KEMPTON PARK  
Gauteng

DEKRA MFC  
M57 Pretoria Rd - 1619  
KEMPTON PARK - GT  
08610 33572



## Assignment

|                 |                   |                     |                          |
|-----------------|-------------------|---------------------|--------------------------|
| Client          | MFC Auction House | Inspection Location | MFC                      |
| Requested Date  | 09/04/2026        |                     | M57 Pretoria Road - 1619 |
| Inspection Date | 09/04/2026        |                     | Kempton Park - GT        |

## Vehicle Data

|                 |                                                     |                         |                   |
|-----------------|-----------------------------------------------------|-------------------------|-------------------|
| Vehicle Type    | PASSENGER VEHICLE                                   | Registered Owner        | MFC               |
| Manufacturer    | VOLKSWAGEN                                          | Registration Number     | KV58VZGP          |
| Model           | GOLF 7 R 2.0 TSI 206KW 4MOTION 5-DR DSG [2015-2017] | Register Number         |                   |
| VIN             | WVWZZZAUZGW161924                                   | Date Of First Licensing |                   |
| Engine Number   |                                                     | Last COR                |                   |
| Doors           | 5                                                   | License Expiry Date     |                   |
| Color           | BLUE                                                | Power / Displacement    |                   |
| Year Model      | 2015                                                | Paint Finish            | TWO COAT METALLIC |
| Km Reading      | 117,198 KM                                          | Fuel                    | PETROL            |
| Cab / Body Type | HATCHBACK                                           | Transmission            | AUTOMATIC         |

## Vehicle Options &amp; Accessories

## Items

## VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za


VIN: WVWZZZAUZGW161924



CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026

|  | Damage                                       | Repair Way                                |
|-----------------------------------------------------------------------------------|----------------------------------------------|-------------------------------------------|
|                                                                                   |                                              |                                           |
|                                                                                   | Engine Oil Leak                              | Repair                                    |
|                                                                                   | Center Console / Cubbyhole + Lid Damaged     | Repair                                    |
|                                                                                   | Tail Light Right Chipped                     | Replace                                   |
|                                                                                   | Seat Front Right Damaged                     | Repair                                    |
|                                                                                   | Front Bumper Damaged                         | Repair                                    |
|                                                                                   | Grill Damaged                                | Replace                                   |
|                                                                                   | Bonnet Residual Traces of Repair             | Repair                                    |
|                                                                                   | Front Fender Right Residual Traces of Repair | Repair                                    |
|                                                                                   | Front Fender Right / Inner Tray Damaged      | Replace                                   |
|                                                                                   | Door Rear Right Residual Traces of Repair    | Repair                                    |
|                                                                                   | Rear bumper Paintwork • Scratched            | Repair                                    |
|                                                                                   | Sill Panel Left Damaged                      | Repair                                    |
|                                                                                   | Engine to silencer pipe Welded               | Replace                                   |
|                                                                                   | Silencer Missing                             | Replace                                   |
|                                                                                   | Belly plates Damaged                         | Repair                                    |
|                                                                                   | Gearbox Oil Leak                             | Repair                                    |
|                                                                                   | Differential Oil Sweat                       | Repair                                    |
|                                                                                   | Engine Smoke Excessive                       | Repair                                    |
|                                                                                   | Jack Missing                                 | Replace                                   |
|                                                                                   | Tyres and rims                               | Spare wheel missing                       |
|                                                                                   | Engine                                       | Signs of vehicle overheating              |
|                                                                                   | Engine                                       | Engine oil sump damaged                   |
|                                                                                   | Tyres and rims                               | Rear left and right tyre sizes different. |
|                                                                                   | Vehicle license disk missing                 | Replace                                   |

Brakes

Brake Test Results

No Brake Test on a brake test machine has been performed.

|                     | Left               | Right              | Axle Weight [KG] | Deceleration [m/s <sup>2</sup> ] |
|---------------------|--------------------|--------------------|------------------|----------------------------------|
|                     | Braking Force [KN] | Braking Force [KN] |                  |                                  |
| Front               | -                  | -                  | -                |                                  |
| Rear                | -                  | -                  | -                |                                  |
| Emergency / Parking | -                  | -                  | -                |                                  |

Tyres and Rims

Tyre Specification & Measurement

|             | Size        | Load/Speed Index | Manufacture | Model     | Type* | Production Date | Tread Depth (mm) |
|-------------|-------------|------------------|-------------|-----------|-------|-----------------|------------------|
| Front Left  | 235/35Z R19 | 91W              | Rapid       | P609      | V     | 2122            | 3 mm             |
| Front Right | 235/35 R19  | 91W              | Yokohama    | Advan     | V     | 5022            | 2 mm             |
| Rear Left   | T125/70 R18 | 99M              | Continental | Temporary | V     | 3915            | 2 mm             |
| Rear Right  | 235/35Z R19 | 91W              | Rapid       | P609      | V     | 4420            | 2 mm             |

\* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: VVWZZZAUZGW161924



## CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026

### Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

| No | System                        | Code    | Description                               | Status |
|----|-------------------------------|---------|-------------------------------------------|--------|
| 1  | 01-ENGINE CONTROL MODULE<br>1 | P011700 | COOLANT TEMPERATURE SENSOR 1, CIRCUIT LOW |        |

### Inspection Conditions

No Test Drive  
Battery Flat  
Engine number – not possible to verify engine number (not visible without dismantling)  
Inspection conditions for the vehicle inspection were sufficient

### Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. Body • Exterior: Poor residual traces of repair on some body panels. Stone chips and spray work on some body panels. Dents and scratches on some body panels. Some body panels misaligned.

### Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

### Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WVVZZZAUZGW161924



## CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026

[illegible]

Shock absorber report

Diagnostic report page 1

[illegible]

Diagnostic report page 2

| 12. 12. 2017 | 13. 12. 2017 | 14. 12. 2017 |
|--------------|--------------|--------------|
| 1. 12. 2017  | 2. 12. 2017  | 3. 12. 2017  |
| 4. 12. 2017  | 5. 12. 2017  | 6. 12. 2017  |
| 7. 12. 2017  | 8. 12. 2017  | 9. 12. 2017  |
| 10. 12. 2017 | 11. 12. 2017 | 12. 12. 2017 |
| 13. 12. 2017 | 14. 12. 2017 | 15. 12. 2017 |
| 16. 12. 2017 | 17. 12. 2017 | 18. 12. 2017 |
| 19. 12. 2017 | 20. 12. 2017 | 21. 12. 2017 |
| 22. 12. 2017 | 23. 12. 2017 | 24. 12. 2017 |
| 25. 12. 2017 | 26. 12. 2017 | 27. 12. 2017 |
| 28. 12. 2017 | 29. 12. 2017 | 30. 12. 2017 |
| 31. 12. 2017 | 1. 1. 2018   | 2. 1. 2018   |
| 3. 1. 2018   | 4. 1. 2018   | 5. 1. 2018   |
| 6. 1. 2018   | 7. 1. 2018   | 8. 1. 2018   |
| 9. 1. 2018   | 10. 1. 2018  | 11. 1. 2018  |
| 12. 1. 2018  | 13. 1. 2018  | 14. 1. 2018  |
| 15. 1. 2018  | 16. 1. 2018  | 17. 1. 2018  |
| 18. 1. 2018  | 19. 1. 2018  | 20. 1. 2018  |
| 21. 1. 2018  | 22. 1. 2018  | 23. 1. 2018  |
| 24. 1. 2018  | 25. 1. 2018  | 26. 1. 2018  |
| 27. 1. 2018  | 28. 1. 2018  | 29. 1. 2018  |
| 30. 1. 2018  | 31. 1. 2018  | 1. 2. 2018   |
| 2. 2. 2018   | 3. 2. 2018   | 4. 2. 2018   |
| 5. 2. 2018   | 6. 2. 2018   | 7. 2. 2018   |
| 8. 2. 2018   | 9. 2. 2018   | 10. 2. 2018  |
| 11. 2. 2018  | 12. 2. 2018  | 13. 2. 2018  |
| 14. 2. 2018  | 15. 2. 2018  | 16. 2. 2018  |
| 17. 2. 2018  | 18. 2. 2018  | 19. 2. 2018  |
| 20. 2. 2018  | 21. 2. 2018  | 22. 2. 2018  |
| 23. 2. 2018  | 24. 2. 2018  | 25. 2. 2018  |
| 26. 2. 2018  | 27. 2. 2018  | 28. 2. 2018  |
| 29. 2. 2018  | 30. 2. 2018  | 31. 2. 2018  |
| 1. 3. 2018   | 2. 3. 2018   | 3. 3. 2018   |
| 4. 3. 2018   | 5. 3. 2018   | 6. 3. 2018   |
| 7. 3. 2018   | 8. 3. 2018   | 9. 3. 2018   |
| 10. 3. 2018  | 11. 3. 2018  | 12. 3. 2018  |
| 13. 3. 2018  | 14. 3. 2018  | 15. 3. 2018  |
| 16. 3. 2018  | 17. 3. 2018  | 18. 3. 2018  |
| 19. 3. 2018  | 20. 3. 2018  | 21. 3. 2018  |
| 22. 3. 2018  | 23. 3. 2018  | 24. 3. 2018  |
| 25. 3. 2018  | 26. 3. 2018  | 27. 3. 2018  |
| 28. 3. 2018  | 29. 3. 2018  | 30. 3. 2018  |
| 31. 3. 2018  | 1. 4. 2018   | 2. 4. 2018   |
| 3. 4. 2018   | 4. 4. 2018   | 5. 4. 2018   |
| 6. 4. 2018   | 7. 4. 2018   | 8. 4. 2018   |
| 9. 4. 2018   | 10. 4. 2018  | 11. 4. 2018  |
| 12. 4. 2018  | 13. 4. 2018  | 14. 4. 2018  |
| 15. 4. 2018  | 16. 4. 2018  | 17. 4. 2018  |
| 18. 4. 2018  | 19. 4. 2018  | 20. 4. 2018  |
| 21. 4. 2018  | 22. 4. 2018  | 23. 4. 2018  |
| 24. 4. 2018  | 25. 4. 2018  | 26. 4. 2018  |
| 27. 4. 2018  | 28. 4. 2018  | 29. 4. 2018  |
| 30. 4. 2018  | 31. 4. 2018  | 1. 5. 2018   |
| 2. 5. 2018   | 3. 5. 2018   | 4. 5. 2018   |
| 5. 5. 2018   | 6. 5. 2018   | 7. 5. 2018   |
| 8. 5. 2018   | 9. 5. 2018   | 10. 5. 2018  |
| 11. 5. 2018  | 12. 5. 2018  | 13. 5. 2018  |
| 14. 5. 2018  | 15. 5. 2018  | 16. 5. 2018  |
| 17. 5. 2018  | 18. 5. 2018  | 19. 5. 2018  |
| 20. 5. 2018  | 21. 5. 2018  | 22. 5. 2018  |
| 23. 5. 2018  | 24. 5. 2018  | 25. 5. 2018  |
| 26. 5. 2018  | 27. 5. 2018  | 28. 5. 2018  |
| 29. 5. 2018  | 30. 5. 2018  | 31. 5. 2018  |
| 1. 6. 2018   | 2. 6. 2018   | 3. 6. 2018   |
| 4. 6. 2018   | 5. 6. 2018   | 6. 6. 2018   |
| 7. 6. 2018   | 8. 6. 2018   | 9. 6. 2018   |
| 10. 6. 2018  | 11. 6. 2018  | 12. 6. 2018  |
| 13. 6. 2018  | 14. 6. 2018  | 15. 6. 2018  |
| 16. 6. 2018  | 17. 6. 2018  | 18. 6. 2018  |
| 19. 6. 2018  | 20. 6. 2018  | 21. 6. 2018  |
| 22. 6. 2018  | 23. 6. 2018  | 24. 6. 201   |

Diagnostic report page 3

[illegible]

Diagnostic report page 4



FRONT RIGHT CORNER

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: WYWZZZAUZGW161924



## CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: VVWZZZAUZGW161924



## CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: VVWZZZAUZGW161924



## CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026



RF TYRE TREAD



Spare wheel Accessories



No license disc



VIN PLATE OR STICKER



ENGINE 1



Front chassis

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: WVVZZZAUZGW161924



## CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026



Rear chassis




Oil cap and dipstick




Engine oil sump



Seat Front Right



Door Rear Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: VVWZZZAUZGW161924



## CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026



Rear bumper



Rear bumper



Tail Light Right



Bonnet



Center Console / Cubbyhole + Lid



Front Bumper

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
www.dekraauto.co.za

VIN: WVVZZZAUZGW161924



## CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026



Front Bumper



Grill



Front Fender Right / Inner Tray



Sill Panel Left



Gearbox



Engine

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksoord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: WVVZZZAUZGW161924



## CONDITION REPORT



Report No:  
2017213531  
DATE  
09/04/2026



Belly plates



Belly plates



Differential



Silencer



Engine to silencer pipe



Water level

DEKRA Automotive (PTY) Ltd.  
97 Willem Cruywagen Ave  
Klerksord, Pretoria, 0200  
Phone: 012 542 4867  
[www.dekraauto.co.za](http://www.dekraauto.co.za)

VIN: WVVZZZAUZGW161924