

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/60/61/64 - Polo/Vento 2010 >/--
VIN: AAVZZZ6RZHU056681

Odometer Reading: 106794
License Plate: FV36SBGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
01 - Engine Control Module 1	 7
02 - Transmission electronics	 1
03 - Brakes 1	 5
15 - Airbag	 1
17 - Instrument cluster	 2
44 - Power steering	 0

DTC (16)

01 - Engine Control Module 1 (7 DTCs)

DTC	Description	Status
P308800	Starter relay Electrical fault in circuit	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic
P003600	02 Sensor Heater Contr. Circ.(Bank1(1)Sensor 2)	Active/static
P030000	Random Misfire Detected No Sub Type Information	Passive/Sporadic
P030300	Cylinder 3 Misfire Detected No Sub Type Information	Passive/Sporadic
P030400	Cylinder 4 Misfire Detected No Sub Type Information	Passive/Sporadic
P007000	Ambient Air Temperature Sensor Circuit	Active/static

02 - Transmission electronics (1 DTC)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic

03 - Brakes 1 (5 DTCs)

DTC	Description	Status
C114602	TPMS Signal error	Active/static
C102D00	Tire pressure warning	Active/static
U110300	Production mode active	Active/static
U042200	Invalid data received from body control unit	Active/static
C10A301	Vacuum sensor Electrical error	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U102100	Body computer 1/ veh. elec sys CM / cent elec. Read out DTC	Active/static

Technician Notes
2017298896

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.