

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZMU009509

Odometer Reading: 101915
License Plate: JX57BDGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	6
03 - Brakes 1	3
09 - Electronic central electric	11
15 - Airbag	6
17 - Instrument cluster	3
19 - Gateway	1
25 - Immobilizer	2
44 - Power steering	2
56 - Radio	3

DTC (37)

01 - Engine Control Module 1 (6 DTCs)

DTC	Description	Status
P1672:00/05 746:000	Fan 1 control circuit Open circuit/short circuit to ground	Passive/Sporadic
P1358:00/04 952:000	Ignition activation cyl. 2 Open circuit	Passive/Sporadic
P1603:00/05 635:000	Ctrl. module faulty	Passive/Sporadic
P0030:00/00 048:000	O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1)	Active/static
P1426:00/05 158:000	Evaporativ Emiss.System Purge Control Valve Circ. Open	Active/static

P0135:00/00	O2 Sensor Heater Circ.,Bank1-Sensor1	Active/static
309:000	Malfunction	

03 - Brakes 1 (3 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic
C101816	Return pump Voltage too low	Active/static

09 - Electronic central electric (11 DTCs)

DTC	Description	Status
01758:011	Lamps for brake lights - Open circuit	Passive/Sporadic
00329:011	Activation for unlocking rear lid - Open circuit	Passive/Sporadic
00975:011	Rear window defogger - Open circuit	Passive/Sporadic
00077:004	Windshield wiper stop switch - No signal/communication	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00538:011	Reference voltage - Open circuit	Passive/Sporadic
01598:000	Drive battery voltage	Passive/Sporadic
02604:000	Message 'Voltage supply too low' from Power Steering Control Module	Passive/Sporadic
03591:006	Signal horn activation - Short circuit to B+	Active/static
03591:011	Signal horn activation - Open circuit	Passive/Sporadic

15 - Airbag (6 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B10001B	Driver airbag igniter Resistance too high	Active/static
B10061B	Driver seat belt tensioner igniter Resistance too high	Active/static
B10021B	Front passenger airbag igniter Resistance too high	Active/static
U140000	Function restriction due to low voltage	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic

17 - Instrument cluster (3 DTCs)

DTC	Description	Status
B103F1B	Exterior temperature sensor Resistance too high	Active/static
U111100	Function restriction caused by missing message	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01316:004	Brake control module - No signal/communication	Passive/Sporadic

25 - Immobilizer (2 DTCs)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic
B104C29	Key Range/performance	Passive/Sporadic

44 - Power steering (2 DTCs)

DTC	Description	Status
U140A00	Terminal 30 Open circuit	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

56 - Radio (3 DTCs)

DTC	Description	Status
00870:011	Left front bass speaker - Open circuit	Active/static
00871:011	Right front bass speaker - Open circuit	Active/static
01044:000	Control module incorrectly coded	Active/static

Technician Notes

2017287377

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.