



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231220140907
Test Time: 2023-12-20 14:09:07
Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZMU018164

Odometer Reading: 51164
License Plate: KF89WRGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V19.00

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 1
09 - Electronic central electric	 1
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 1
25 - Anti-Theft Immobilizer	 0
44 - Power Steering	 0
56 - Radio	 1

DTC (5)

03 - Brakes 1 (1 DTC)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic

09 - Electronic central electric (1 DTC)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic



19 - Gateway (1 DTC)

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

56 - Radio (1 DTC)

DTC	Description	Status
01044:000	Control module incorrectly coded -	Passive/Sporadic

Technician Notes

2016207780

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.