

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
 VIN: AAVZZZ6RZPU022469

Odometer Reading: 254631
 License Plate: LK46KMGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
 Version: V25.00

Serial Number: VB8GJCC01509
 Repair Order Number: --

System Scanned (9)

System	Status/DTC
01 - Engine Control Module 1	4
03 - Brakes 1	2
09 - Electronic central electric	3
15 - Airbag	7
17 - Instrument cluster	1
19 - Gateway	1
25 - Immobilizer	2
44 - Power steering	3
56 - Radio	3

DTC (26)

01 - Engine Control Module 1 (4 DTCs)

DTC	Description	Status
P1603:00/05 635:000	Ctrl. module faulty	Passive/Sporadic
P0303:00/00 771:000	Cyl.3 Misfire Detected	Passive/Sporadic
P0300:00/00 768:000	Random/Multiple Cylinder Misfire Detected	Passive/Sporadic
P1609:00/05 641:000	Crash shut-off was triggered	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic

C101C29	Left rear Wheel Speed Sensor (WSS) Range/performance	Active/static
---------	---	---------------

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
01598:000	Drive battery voltage	Passive/Sporadic

15 - Airbag (7 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B10061B	Driver seat belt tensioner igniter Resistance too high	Active/static
B200600	Control module does not match vehicle	Passive/Sporadic
B101600	Front passenger airbag off indicator	Passive/Sporadic
B10071B	Front passenger side seat belt tensioner igniter Resistance too high	Active/static
B102900	Rear crash data stored	Active/static
U112100	Data bus message missing	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U111100	Function restriction caused by missing message	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

25 - Immobilizer (2 DTCs)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic
B104D00	Incorrect key programming	Active/static

44 - Power steering (3 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
U140A00	Terminal 30 Open circuit	Passive/Sporadic

U101100	Supply voltage Voltage too low	Passive/Sporadic
---------	-----------------------------------	------------------

56 - Radio (3 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
01044:000	Control module incorrectly coded	Active/static

Technician Notes
2017299375

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.