

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
 VIN: AAVZZZ6SZEU022520

Odometer Reading: 292163
 License Plate: HM30RFGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V19.00

Serial Number: VB8GJCC01482
 Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	0
03 - Brakes 1	2
09 - Electronic central electric	1
15 - Airbag	2
17 - Instrument cluster	1
19 - Gateway	0
25 - Anti-Theft Immobilizer	0
44 - Power Steering	0
46 - Comfort System Central Control Module	0
56 - Radio	0

DTC (6)

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
00285:008	Right front ABS wheel speed sensor - Implausible signal	Active/static
18055:000	Checking coding/versions of control modules in drivetrain -	Active/static

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01598:007	Drive battery voltage - Signal too low	Passive/Sporadic

15 - Airbag (2 DTCs)

DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic
00588:032	Driver side airbag igniter - Resistance too high	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
01314:049	Engine control unit - No communication	Passive/Sporadic

Technician Notes

2016204900

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.