

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--

VIN: AAVZZZ6SZHU006451

Odometer Reading: 117201

License Plate: FS12CZGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V25.00

Repair Order Number: --



System Scanned (11)

System	Status/DTC
01 - Engine Control Module 1	 4
03 - Brakes 1	 1
09 - Electronic central electric	 2
15 - Airbag	 1
17 - Instrument cluster	 2
19 - Gateway	 1
25 - Immobilizer	 0
44 - Power steering	 2
45 - Interior Monitoring	 0
46 - Comfort System Central Control Module	 0
56 - Radio	 0



DTC (13)

01 - Engine Control Module 1 (4 DTCs)

DTC	Description	Status
P0073:00/00 115:000	Ambient Air Temperature Sensor Circuit High	Active/static
P1660:00/05 728:000	Cooling Fan 1 Control Circuit Low	Passive/Sporadic
P0030:00/00 048:000	O2 Sensor Heater Contr. Circ.(Bank1(1)Sensor 1)	Active/static
P0135:00/00 309:000	O2 Sensor Heater Circ.,Bank1-Sensor1 Malfunction	Active/static

03 - Brakes 1 (1 DTC)

DTC	Description	Status
00283:008	Left front ABS wheel speed sensor - Implausible signal	Active/static

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
01598:027	Drive battery voltage - Implausible signal	Passive/Sporadic
01309:049	Power steering control module - No communication	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
65535:000	Ctrl. module faulty	Active/static
01309:049	Power steering control module - No communication	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01309:049	Power steering control module - No communication	Passive/Sporadic

44 - Power steering (2 DTCs)

DTC	Description	Status
U140A00	Terminal 30 Open circuit	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

Technician Notes
2017284338

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.