

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
 VIN: AAVZZZ6SZHU033010

Odometer Reading: 228322
 License Plate: NB10655

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V19.00

Serial Number: VB8GJCC01482
 Repair Order Number: --

System Scanned (10)

| System | Status/DTC |
|--|------------|
| 01 - Engine Control Module 1 | 1 |
| 03 - Brakes 1 | 0 |
| 09 - Electronic central electric | 2 |
| 15 - Airbag | 4 |
| 17 - Instrument cluster | 1 |
| 19 - Gateway | 1 |
| 25 - Anti-Theft Immobilizer | 0 |
| 44 - Power Steering | 0 |
| 46 - Comfort System Central Control Module | 0 |
| 56 - Radio | 0 |

DTC (9)

01 - Engine Control Module 1 (1 DTC)

| DTC | Description | Status |
|------------------------|---|------------------|
| U0151:00/49 489:000 | Lost Communication With Restraints Control Module - | Passive/Sporadic |

09 - Electronic central electric (2 DTCs)

| DTC | Description | Status |
|-----------|--|------------------|
| 01321:049 | Airbag control module - No communication | Passive/Sporadic |
| 01598:007 | Drive battery voltage - Signal too low | Passive/Sporadic |

15 - Airbag (4 DTCs)

| DTC | Description | Status |
|-----------|--|------------------|
| 00588:033 | Driver side airbag igniter - Resistance too low | Active/static |
| 00589:033 | Front passenger side airbag igniter 1 - Resistance too low | Active/static |
| 00532:007 | Supply voltage - Signal too low | Passive/Sporadic |
| 01312:037 | Drive train data bus - Faulty | Passive/Sporadic |

17 - Instrument cluster (1 DTC)

| DTC | Description | Status |
|-----------|--|------------------|
| 01321:049 | Airbag control module - No communication | Passive/Sporadic |

19 - Gateway (1 DTC)

| DTC | Description | Status |
|-----------|--|------------------|
| 01321:049 | Airbag control module - No communication | Passive/Sporadic |

Technician Notes

2016204981

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.