

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AE/AW - Polo 2017 >/--
VIN: AAVZZZAW4RU106838

Odometer Reading: 62890km
License Plate: LY45SDGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned (21)

System	Status/DTC
01 - Engine Control Module 1	 21
02 - Transmission electronics	 1
03 - Brakes 1	 13
08 - Air conditioning	 1
09 - Electronic central electric	 4
13 - Adaptive cruise control	 2
14 - Wheel Damping Electronics	 0
15 - Airbag	 2
17 - Instrument cluster	 2
19 - Gateway	 2
2B - Steering Column Locking	 0
44 - Power steering	 1
55 - Headlamp range control	 1
5F - Information electronics 1	 3
76 - Parking aid	 0
A5 - Front sensor for driver assistance systems	 1
A9 - Structure-Borne Sound Actuator	 0
B7 - Interface for access/start system	 2
CA - Sunroof control module	 0
D6 - Light control left 2	 0

D7 - Light control right 2

 1 **DTC (57)****01 - Engine Control Module 1 (21 DTCs)**

DTC	Description	Status
P305400	Starter does not turn Mechanically blocked or electrical malfunction	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
P167E00	Start/stop restart Maximum start time exceeded	Passive/Sporadic
P056200	System Voltage Low Voltage	Passive/Sporadic
P029900	Turbocharger/supercharger underboost	Passive/Sporadic
P332500	Voltage supply Kl.15 implausible	Passive/Sporadic
P050100	Vehicle speed sensor A Range/performance	Passive/Sporadic
P050600	Idle control system Speed lower than specified value	Passive/Sporadic
P008A00	Low Pressure Fuel System Pressure - Too Low	Passive/Sporadic
P310B00	Fuel low pressure regulation Fuel pressure out of range	Passive/Sporadic
P017200	Fuel Trim,Bank1 System too Rich	Passive/Sporadic
P217700	System too lean off idle, Bank 1	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P014100	O2 Sensor Heater Circ.,Bank1-Sensor2 Malfunction	Passive/Sporadic
P30C000	Fuel quality Poor	Passive/Sporadic
P030000	Random Misfire Detected No Sub Type Information	Passive/Sporadic
P030100	Cylinder 1 Misfire Detected No Sub Type Information	Passive/Sporadic
P030300	Cylinder 3 Misfire Detected No Sub Type Information	Passive/Sporadic

P030200	Cylinder 2 Misfire Detected No Sub Type Information	Passive/Sporadic
P130A00	Cylinder suppression	Passive/Sporadic
P125000	Fuel level too low	Active/static

02 - Transmission electronics (1 DTC)

DTC	Description	Status
P056200	System Voltage Low Voltage	Passive/Sporadic

03 - Brakes 1 (13 DTCs)

DTC	Description	Status
P147900	Brake vacuum system mechanical malfunction	Passive/Sporadic
C131900	ESC temporarily not available	Passive/Sporadic
P056200	System Voltage Low Voltage	Passive/Sporadic
B1872F1	internal power supply Malfunction	Passive/Sporadic
C106B29	Wheel Speed Sensor (WSS) Range/performance	Passive/Sporadic
U042300	Invalid data received from Instrument cluster control unit	Passive/Sporadic
C05A400	Wheel speed sensor Supply voltage too low	Passive/Sporadic
B106FF0	Function restriction caused by excessive brake temperature	Passive/Sporadic
C11EEF7	Time delay function implausible condition	Passive/Sporadic
C102DF5	Tire pressure warning Tire pressure too low	Passive/Sporadic
U045200	Invalid data received from restraints control unit	Passive/Sporadic
B200FF0	Internal malfunction	Passive/Sporadic
C135DF1	Power steering control module does not implement request	Passive/Sporadic

08 - Air conditioning (1 DTC)

DTC	Description	Status
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (4 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B147918	Remote control vehicle key 1 Insufficient current	Active/static
B147A18	Remote control vehicle key 2 Insufficient current	Active/static
B173011	Relay output heated exterior mirror Short circuit to Ground (GND)	Passive/Sporadic

13 - Adaptive cruise control (2 DTCs)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic

15 - Airbag (2 DTCs)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U111000	Function restriction due to communication interruption	Passive/Sporadic
U167900	Distance Calculation faulty	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic
U112100	Data bus message missing	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

55 - Headlamp range control (1 DTC)

DTC	Description	Status
-----	-------------	--------

U120100	Data bus No communication	Passive/Sporadic
---------	------------------------------	------------------

5F - Information electronics 1 (3 DTCs)

DTC	Description	Status
B129B13	Microphone 1 Open circuit	Passive/Sporadic
B10CD00	Function restriction caused by energy management	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic

A5 - Front sensor for driver assistance systems (1 DTC)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic

B7 - Interface for access/start system (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

D7 - Light control right 2 (1 DTC)

DTC	Description	Status
U120100	Data bus No communication	Passive/Sporadic

Technician Notes
2017297167

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.