

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ADMNRCHR9G4793935

Odometer Reading: 327947
License Plate: KKR635MP

Customer Information

Name: --

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V5.61

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (4)

System	Status/DTC
ABS(Anti-lock Brake System)	 13
SRS(Supplemental Restraint System)	 1
IMMO(Immobilizer)	 0
SCD(Speedometer Control Device)	 0

DTC (14)

ABS(Anti-lock Brake System) (13 DTCs)

DTC	Description	Status
C0040_18	Right front abnormal wheel speed variation B	Not present
C0040_06	Right front wheel speed sensor (WSS) circuit fault	Present
C0035_06	Left front wheel speed sensor (WSS) circuit fault	Present
C0050_06	Right rear wheel speed sensor (WSS) circuit fault	Present
C0045_06	Left rear wheel speed sensor (WSS) circuit fault	Present
C0800_03	Voltage drop detection	Not present
C0161_00	Brake switch circuit fault (ABS/ESC)	Not present
C0186_3B	G sensor data internal invalid fault	Not present
U0100_00	Communication fault with engine ECU	Not present
U0140_00	Communication fault with meter ECU	Not present
U0100_71	ECM information invalid error	Not present
C0710_4B	Steering angle sensor (SAS) center position invalid fault	Present
C0196_3B	Yaw rate sensor (YRS) data invalid status	Not present

SRS(Supplemental Restraint System) (1 DTC)

DTC	Description	Status
B1325_03	Battery voltage too low	Not present

Technician Notes

2017283750

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.