

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ADMNRRHR7G4793421

Odometer Reading: 239896
License Plate: FP50ZJGP

Customer Information

Name: --

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V5.61

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
ECM(Engine Control Module)	 1
ABS(Anti-lock Brake System)	 5
SRS(Supplemental Restraint System)	 0
IMMO(Immobilizer)	 0
SCD(Speedometer Control Device)	 0

DTC (6)

ECM(Engine Control Module) (1 DTC)

DTC	Description	Status
P0661	Intake manifold tuning valve control circuit low	Not present

ABS(Anti-lock Brake System) (5 DTCs)

DTC	Description	Status
C0035_00	Left front abnormal wheel speed variation A	Not present
C0800_03	Voltage drop detection	Not present
C0161_00	Brake switch circuit fault (ABS/ESC)	Not present
C0196_03	Yaw rate sensor (YRS) power source voltage fault	Not present
U0100_71	ECM information invalid error	Not present

Technician Notes

2017298899

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.