

Shop Name: Dekra MFC Auction House Tel: --Email: --Address: MFC AUCTION HOUSE M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20250313094820 Test Time: 2025-03-13 09:48:20 Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--VIN: AHTSS22P707103130

Customer Information

Name: Dekra MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT Version: V11.20 Odometer Reading: 328371km License Plate: JC30MMGP

Tel: 0861033572

Serial Number: VB8GJCC01514 Repair Order Number: --

🔁 System Scanned(5)

System	Status/DTC
Engine and ECT	📀 0
ABS/VSC/TRC	3
SRS airbag	S 5
Combination meter	3 4
Immobilizer	O

🔼 DTC (12)

ABS/VSC/TRC (3 DTCs)

DTC	Description	Status		
C0278	ABS solenoid relay circuit open	Current		
C1241	Low or high power supply voltage	Current		
C1249	Stop lamp switch circuit open	Current		
SRS airbag (5 DTCs)				
DTC	Description	Status		
B1801	Driving side squib circuit open	Current		
B1803	Driver squib circuit short to battery (+)	Current		
B1801	Driving side squib circuit open	History		
B1803	Driver squib circuit short to battery (+)	History		
B1806	P squib circuit open	History		
Combination meter (4 DTCs)				
DTC	Description	Status		
U0100	Lost communication with ECM/PCM/EV "A"	History		
U0129	Lost communication with brake system control module	History		

/Toyota/Hiace/	Ventury	Test Time: 2025-03-13 09:48:20	Report ID: MAXIA20250313094820
B1507	Turn signal circuit open		History
B1508	Turn signal/hazard flasher circuit short		History
Technician I 2016799475	Notes		
		Customer name:	
		Technician:	
		Date:	

Note:Please save a copy of this report for your records.