

Mahindra VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mahindra/Xuv300/--
 VIN: MA1NY2NWPS2056573

Odometer Reading: 90684
 License Plate: HJG008L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
 Version: V3.10

Serial Number: VB8GJCC01509
 Repair Order Number: --

System Scanned (9)

System	Status/DTC
Engine management system	5
Anti-Lock braking system / Electronic stability program	5
Supplementary restraint system	6
Fully automated temperature control / Electronic temperature control	4
Electronic power steering	1
Mahindra body function module	8
Passive keyless entry	4
Infotainment system	10
Electrical steering colum lock	0

DTC (43)

Engine management system (5 DTCs)

DTC	Description	Status
U206C00	Please refer to vehicle service manual.	History
U110500	IC Node Absent	History
U110800	IS Node Absent	History
U20AB00	ESC TRQ_DECR_REQ_FAST Signal Content Error	History
P063200	Odometer value coming less than stored value	History

Anti-Lock braking system / Electronic stability program (5 DTCs)

DTC	Description	Status
C004012	BLA active; feedback is not active	Current
C010111	BLA relay SCG	Current

C111400	EPS status defective	History
C114446	Please refer to vehicle service manual.	History
U211C00	Please refer to vehicle service manual.	History

Supplementary restraint system (6 DTCs)

DTC	Description	Status
B101349	Autoliv ECU internal error	Other
B142A16	Battery voltage low	Other
U200300	Please refer to vehicle service manual.	Healed
U205300	Please refer to vehicle service manual.	Other
U205400	Please refer to vehicle service manual.	Other
U205900	Please refer to vehicle service manual.	Other

Fully automated temperature control / Electronic temperature control (4 DTCs)

DTC	Description	Status
B134816	ECU undervoltage	History
U110500	Cluster node absent	Other
U110800	IS node absent	Other
U200300	CURRENT_GEAR_MT Signal Content Failure	Healed

Electronic power steering (1 DTC)

DTC	Description	Status
U20B300	STR_TRQ_REQ signal invalid	Healed

Mahindra body function module (8 DTCs)

DTC	Description	Status
B110515	Left rear turn lamp circuit open or short to battery	Other
B110615	Right rear turn lamp circuit open or short to battery	Other
B112931	Front Right TPMS Sensor Signal Missing Fault	Current
B115429	Invalid crash Input from Airbag ECU	Other
B117715	Rear Park LED Short circuit to battery or Open circuit error	Other
B118C9E	Auto washer switch stuck	Other
U115000	HLCU1 Node Absent	Other
U115500	HLCU2 node Absent	Other

Passive keyless entry (4 DTCs)

DTC	Description	Status
B12F516	Battery undervoltage	Other
B133016	Key fob battery low	Healed
U20D200	Instrument Cluster (IC) fuel level signal content fault	Other

U200300	EMS Current Gear Signal Content Error	Healed
---------	---------------------------------------	--------

Infotainment system (10 DTCs)

DTC	Description	Status
B202416	Please refer to vehicle service manual.	Others
B101511	Please refer to vehicle service manual.	Others
B202347	Please refer to vehicle service manual.	Others
B203500	Please refer to vehicle service manual.	Healed
B147255	Please refer to vehicle service manual.	Current
U200300	EMS current gear signal content error (Signal invalid)	Healed
U20D600	Please refer to vehicle service manual.	Current
U20D700	Please refer to vehicle service manual.	Current
U20D800	Please refer to vehicle service manual.	Current
U20D900	Please refer to vehicle service manual.	Current

Technician Notes

2017296633

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.