

Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/EcoSport/--
VIN: MAJAXXMRKADA32926

Odometer Reading: 256747km
License Plate: CT97NCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
PCM(Powertrain control module)	 2
ABS(Anti-lock brake system)	 0
RCM(Restraint control module)	 0
IPC(Instrument panel control module)	 1
ACM(Audio control module)	 0
APIM(Accessory protocol interface module)	 0
BdyCM(Body control module)	  1
FCDIM(Front control/display interface module)	 0
PSCM(Power steering control module)	 0

DTC (4)

PCM(Powertrain control module) (2 DTCs)

DTC	Description	Status
P0112:00-AE	Intake Air Temperature Sensor 1 Circuit Low (Bank 1)	CMDTCs
P2269:00-2F	Water in Fuel Condition - Sensor A	CMDTCs

IPC(Instrument panel control module) (1 DTC)

DTC	Description	Status
U0257:00-08	Lost Communication With Front Controls / Display Interface Module	CMDTCs

BdyCM(Body control module) (1 DTC)

DTC	Description	Status
B1D00:15-48	Left Low Beam	CMDTCs

Technician Notes

2017287189

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.