

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Grand i10/Xcent (BA)/--
VIN: MALA851ALLM059589

Odometer Reading: 150366
License Plate: JL33KYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
ENG (Engine)	 1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 2
AB (Airbag)	 1
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

DTC (4)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0562	System voltage low	History

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1102	Battery voltage low	History
C1203	Right front vehicle speed sensor (VSS) circuit open or short	Active

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

Technician Notes

2017297675

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.