

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i10(IA)/--
VIN: MALAN51BLDM362955

Odometer Reading: 145534
License Plate: CL37HCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.10

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (2)

System	Status/DTC
ENG (Engine)	 2
IMMO (Immobilizer)	 0

DTC (2)

ENG (Engine) (2 DTCs)

DTC	Description	Status
P0134	Oxygen sensor circuit no activity detected (Bank 1 sensor 1)	Pending
P0340	Intake camshaft position (CMP) sensor 'A' circuit (Bank 1 or single sensor)	History

Technician Notes

2017297774

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.