

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Swift/--
VIN: MBHCZF63S00258751

Odometer Reading: 131976
License Plate: FVW994L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	 1
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	 4
SRS(Airbag)	 0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	 5
CGW(Central gateway control module)	 1
EPS(Power steering)	 0
BCM(Body Control Module)	 1
SMK(Immobilizer and/or keyless system)	 1

DTC (13)

ECM/PCM(Engine/powertrain) (1 DTC)

DTC	Description	Status
P0011	A Camshaft Position (CMP) timing over-advanced or system performance (bank 1)	Current

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (4 DTCs)

DTC	Description	Status
C1091	CAN invalid data from ECM	History
C1057	Power supply voltage	History
C1037	Steering angle sensor power supply voltage	History
U0100	Lost communication with ECM	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (5 DTCs)

DTC	Description	Status
B1840	Vehicle speed data invalid	History

U0100	Lost communication with ECM	History
U0121	Lost communication with ABS or electronic stability program control module	History
U0131	Lost communication with Power Steering Control Module (PSCM)	History
U0151	Lost communication with restraints control module	History

CGW(Central gateway control module) (1 DTC)

DTC	Description	Status
U0100-87	Lost communication with ECM	History

BCM(Body Control Module) (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM	History

SMK(Immobilizer and/or keyless system) (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM	History

Technician Notes

2017295103

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.