

# Renault VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Renault/KWID/--  
VIN: MEEBBA00200642342

Odometer Reading: 95817km  
License Plate: CN83LYZN

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT  
Version: V17.50

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned ( 5 )

| System                              | Status/DTC                                                                              |
|-------------------------------------|-----------------------------------------------------------------------------------------|
| INJ(Injection)                      |  4   |
| ABG(Airbag / pretensioners)         |  1   |
| TDB(Instrument panel)               |  4   |
| UCH(Central control unit)           |  2   |
| DAV(Variable power assist steering) |  1 |

## DTC ( 12 )

### INJ(Injection) ( 4 DTCs )

| DTC       | Description                                           | Status |
|-----------|-------------------------------------------------------|--------|
| DTC013013 | Upstream oxygen sensor circuit<br>Open circuit        | Memory |
| DTC033531 | Engine speed sensor signal<br>No signal               | Memory |
| DTC033564 | Engine speed sensor signal<br>Plausibility.           | Memory |
| DTC065711 | Main relay control circuit<br>Short circuit to earth. | Active |

### ABG(Airbag / pretensioners) ( 1 DTC )

| DTC       | Description                                                                                                                                                          | Status |
|-----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|
| DTC80D224 | Warning light circuit fault<br>Inconsistency between the warning light status<br>transmitted by the instrument panel and the request made<br>by the airbag computer. | Memory |

### TDB(Instrument panel) ( 4 DTCs )

| DTC | Description | Status |
|-----|-------------|--------|
|-----|-------------|--------|

|           |                                                        |        |
|-----------|--------------------------------------------------------|--------|
| DTC94037B | Brake fluid level circuit<br>Below the min level       | Memory |
| DTC941111 | Oil pressure sensor circuit<br>Short circuit to earth. | Memory |
| DTCC00187 | CAN communication<br>Signal missing.                   | Memory |
| DTCF00316 | Battery voltage 12 V<br>Feed voltage too low           | Memory |

UCH(Central control unit) ( 2 DTCs )

| DTC       | Description                                                | Status |
|-----------|------------------------------------------------------------|--------|
| DTC953118 | Right indicator circuit<br>Circuit current below threshold | Memory |
| DTC95F031 | Transponder supply circuit<br>No signal                    | Memory |

DAV(Variable power assist steering) ( 1 DTC )

| DTC       | Description                             | Status |
|-----------|-----------------------------------------|--------|
| DTC560849 | Computer<br>Internal electronic failure | Memory |

Technician Notes  
2017296820

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.