

Jaguar VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Jaguar/F-Pace (X761)/--
VIN: SADCA2AN6KA608770

Odometer Reading: 101470
License Plate: KLJ021NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.10

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned (26)

System	Status/DTC
PCM (Powertrain Control Module)	 15
TCM (Transmission Control Module)	 1
ABS (Anti-Lock Brake System Control Module)	 1
RCM (Restraints Control Module)	 0
IPC (Instrument Panel Cluster Control Module)	 0
BCM (Body Control Module)	 1
TCCM (Transfer Case Control Module)	 0
GWM (Gateway Module 'A')	 0
HVAC (HVAC Control Module)	 1
SASM (Steering Angle Sensor Module)	 0
DDM (Driver Front Door Module)	 1
PDM (Passenger Front Door Module)	 1
DSM (Driver Front Seat Module)	 0
DRDM (Driver Rear Door Module)	 0
PRDM (Passenger Rear Door Module)	 0
AAM (Audio Amplifier Module)	 4
ATCM (All Terrain Control Module)	 0
FCIM (Front Controls Interface Module)	 1
GSM (Gear Shift Module)	 0
IMC (Infotainment Master Controller)	 5

IPMA (Image Processing Module 'A')	ADAS	 3
IPMB (Image Processing Module 'B')	ADAS	 4
PAM (Parking Assist Control Module)	ADAS	 0
PSCM (Power Steering Control Module)		 4
RFA (Remote Function Actuator)		 0
TCU (Telematic Control Unit Module)		 3

DTC (45)

PCM (Powertrain Control Module) (15 DTCs)

DTC	Description	Status
B10A2-26	Crash input - Signal change rate below threshold	History
U0151-08	Lost communication with Restraints Control Module (RCM) - Bus signal/message faults	History
B10A2-32	Crash input - Signal low time below minimum	History
U2012-56	Vehicle configuration parameter - Invalid/incompatible configuration	History
P0480-71	Cooling fan 1 control circuit fault - Actuator stuck	History
U0080-87	Vehicle communication bus F - Missing message	History
U0101-87	Lost communication with Transmission Control Module (TCM) - Missing message	History
P025C-11	Fuel pump control module circuit low - Circuit short to ground	History
U0080-82	Vehicle communication bus F - Alive/sequence counter incorrect/not updated	History
U0405-68	Invalid data received from speed control module - Event information	Permanent
U0080-81	Vehicle communication bus F - Invalid serial data received	History
P0030-29	Heated Oxygen Sensor (HO1S) heater control circuit (bank 1 sensor 1) - Signal invalid	History
P0602-00	Internal control module programming error - No sub type information	History
U0167-00	Lost communication with vehicle immobilizer control module - No sub type information	History
P0671-13	Cylinder 1 glow plug circuit/open - Open circuit	Permanent

TCM (Transmission Control Module) (1 DTC)

DTC	Description	Status
-----	-------------	--------

P0702-04	Transmission control system electrical - System internal faults	Permanent
----------	---	-----------

ABS (Anti-Lock Brake System Control Module) (1 DTC)

DTC	Description	Status
U0080-81	Vehicle communication bus F - Invalid serial data received	Permanent

BCM (Body Control Module) (1 DTC)

DTC	Description	Status
B13CB-87	Roof blind module - Missing message	History

HVAC (HVAC Control Module) (1 DTC)

DTC	Description	Status
U3000-87	Control module - Missing message	History

DDM (Driver Front Door Module) (1 DTC)

DTC	Description	Status
B1207-29	Crash input hardwired signal - Signal invalid	Permanent

PDM (Passenger Front Door Module) (1 DTC)

DTC	Description	Status
B1207-29	Crash input hardwired signal - Signal invalid	Permanent

AAM (Audio Amplifier Module) (4 DTCs)

DTC	Description	Status
B1A05-12	Speaker 5 circuit - Circuit short to battery	Permanent
B1A07-12	Speaker 7 circuit - Circuit short to battery	Permanent
B1D9F-13	Engine speed input - Open circuit	Permanent
B1D9F-11	Engine speed input - Circuit short to ground	Permanent

FCIM (Front Controls Interface Module) (1 DTC)

DTC	Description	Status
U2300-54	Central configuration - Missing calibration	History

IMC (Infotainment Master Controller) (5 DTCs)

DTC	Description	Status
B1087-83	LIN bus A - Value of signal protection calculation incorrect	Permanent
B1087-87	LIN bus A - Missing message	Permanent
B137F-31	Steering wheel - left switch cluster - No signal	Permanent
B14B4-15	Bluetooth antenna 1 - Circuit short to battery or open	Permanent
U2016-68	Control module main software - Event information	Permanent

IPMA (Image Processing Module 'A') (3 DTCs)

DTC	Description	Status
U3003-16	Battery voltage - Circuit voltage below threshold	Permanent

U0001-81	High speed CAN communication bus - Invalid serial data received	History
C1001-78	Vision system camera - Alignment or adjustment incorrect	Permanent

IPMB (Image Processing Module 'B') (4 DTCs)

DTC	Description	Status
B100E-29	Video input A - Signal invalid	History
B14AD-31	Touch screen - No signal	History
U1A4B-49	Control module processor B - Internal electronic fault	History
U3000-16	Control module - Circuit voltage below threshold	Permanent

PSCM (Power Steering Control Module) (4 DTCs)

DTC	Description	Status
U0001-81	High speed CAN communication bus - Invalid serial data received	Permanent
U2100-56	Initial configuration not completed - Invalid/incompatible configuration	Permanent
U2300-54	Central configuration - Missing calibration	Permanent
U3001-00	Control module improper shutdown (voltage related) - No sub type information	Permanent

TCU (Telematic Control Unit Module) (3 DTCs)

DTC	Description	Status
B14A9-13	BroadR-Reach link - telematics (+) - Open circuit	Permanent
B14AA-13	BroadR-Reach link - telematics (-) - Open circuit	Permanent
U2300-56	Central configuration - Invalid/incompatible configuration	Permanent

Technician Notes
2017278310

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.